

Technical Service Bulletin (TSB)

Flash: Central ADAS Decision Module (CADM) Updates

REFERENCE:	TSB: 08-013-26 GROUP: 08 - Electrical	Date:	January 17, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 (WL) Jeep Grand Cherokee / Grand Cherokee L This bulletin applies to vehicles built on or after August 25, 2025 (MDH 0825XX) and on or before December 05, 2025 (MDH 1205XX) equipped with Active Driving Assist System (Sales Code SJJ) without Hands-Free Active Driving Assist Sys (Sales Code SJH) and or Classic Theme (Sales Code CEV).			MARKET APPLICABILITY: ☒ NA☒ MEA ☒ SA☒ IAP ☒ EE☐ CH NOTE: This bulletin applies to North and South America, Enlarged Europe, Middle East & Africa and India & Asia Pacific markets.	
CUSTOMER SYMPTOM:	Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set at least one of the following Diagnostic Trouble Codes (DTCs): - C2203-00 - Current VIN Missing/Mismatch. - C008E-00 - ECU Internal Performance with Environmental Data Decode Byte: APP_FATAL_ERROR_APP_CONFIGURATION_ERROR_FAULT. Customers may also comment on one or more of the following: - The Instrument Panel Cluster (IPC) is displaying one or more of the following messages: "ACC/FCW Unavailable Service Required". "ACC/FCW Limited Functionality". "Active Lane Management Limited Functionality." "Active Lane Management Unavailable Service Required". "Automatic Emergency Braking (AEB) Limited Service Required". "AEB Unavailable Service Required". "Blindspot Detection Unavailable Service Required" "Blindspot Detection Limited Functionality" - Customer states that the ADAS features are disabled.				
CAUSE:	CADM software				

REPAIR SUMMARY:

This bulletin involves reprogramming of the CADM with the latest available software and possibly performing the Forward Facing Camera Dynamic Service Alignment/Calibration routine.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-41-9Q	Central ADAS Decision Module (CADM) - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
Failure Code	CC	Customer Concern	

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

RELATED LOP(S):

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-41-50	Perform Forward Facing Camera Dynamic Service Alignment/Calibration (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above and DTC C2203-00 - Current VIN Missing/Mismatch is present proceed to the Repair Procedure.

If the customer describes any of the symptoms listed above and C008E-00 - ECU Internal Performance DTC is present, this requires additional steps for proper diagnosis.

Please reference the additional diagnosis steps below on how to view the Environmental Data. The Environmental Data is needed to confirm the APP_FATAL_ERROR_APP_CONFIGURATION_ERROR_FAULT decode byte as shown in the [Fig. 1](#).

CADM | C008E-00 | Active | ECU Internal Performance

NAME	VALUE	UNITS
Internal DTC Decode Byte 1	EyeQ_Fatal_Error	
Internal DTC Decode Byte 2	APP_FATAL_ERROR_APP_CONFIGURATION_ERROR_FAULT	
Internal DTC Decode Byte 3	Not Applicable	
System Voltage	12.1	V
DTC_Reason_Byte1 (Most Recent)	NOT_APPLICABLE_RSN	
Most Recent Internal Temperature	-8	°F
Internal DTC Decode Byte 1	EyeQ_Fatal_Error	
Internal DTC Decode Byte 2	APP_FATAL_ERROR_APP_CONFIGURATION_ERROR_FAULT	
Internal DTC Decode Byte 3	Not Applicable	

Fig. 1
CADM DTC Environmental Data View

1. Using the wiTECH, select "ECU List" under Vehicle.

2. Select "CADM - Central ADAS Decision Module".
3. Select "DTCs".
4. View the CADM DTC "C008E-00 - ECU Internal Performance".
5. Hover over the CADM DTC "C008E-00 - ECU Internal Performance" and then select it to view the DTC's environmental data.
6. Confirm that Internal DTC Decode Byte "APP_FATAL_ERROR_APP_CONFIGURATION_ERROR_FAULT" is present and proceed to the [Repair Procedure](#).

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	–	–

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

NOTE: Replacement of the CADM or the LRCF is NOT necessary for these conditions.

1. Reprogram the CADM with the latest software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.
2. Using the wiTECH, reset the CADM module. The reset procedure can be found in Guided Diagnostics > Reset ECU > CADM.
3. Is DTC "C008E-00 - ECU Internal Performance" set?
 - YES>>> Proceed to [Step 4](#).
 - NO>>> Proceed to [Step 6](#).
4. Navigate to the CADM "Misc Functions" menu.
5. To calibrate the LRCF, select and perform the "Forward Facing Camera Dynamic Service Alignment/ Calibration" routine located under the CADM "Misc Functions" menu.
6. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

NOTE: For SA market only, after applying this TSB, it is not necessary to send DID-1 or DID-A.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.