



Service Bulletin

Bulletin No.: PIP6099A

Date: January, 2026

PRELIMINARY INFORMATION

Subject: DTC P16F4 "Service Transmission" Message on DIC

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2026		ALL	ALL	ALL	ALL
Buick	Envision	2026		ALL	ALL	ALL	ALL
Cadillac	Escalade	2026		ALL	ALL	ALL	ALL
Cadillac	ESCALADE IQ	2026		ALL	ALL	ALL	ALL
Cadillac	LYRIQ	2026		ALL	ALL	ALL	ALL
Cadillac	OPTIQ	2026		ALL	ALL	ALL	ALL
Cadillac	VISTIQ	2026		ALL	ALL	ALL	ALL
Chevrolet	Blazer EV	2026		ALL	ALL	ALL	ALL
Chevrolet	Brightdrop	2026		ALL	ALL	ALL	ALL
Chevrolet	Equinox	2026		ALL	ALL	ALL	ALL
Chevrolet	Equinox EV	2026		ALL	ALL	ALL	ALL
Chevrolet	Silverado EV	2026		ALL	ALL	ALL	ALL
Chevrolet	Suburban	2026		ALL	ALL	ALL	ALL
Chevrolet	Tahoe	2026		ALL	ALL	ALL	ALL
Chevrolet	Traverse	2026		ALL	ALL	ALL	ALL
GMC	Acadia	2026		ALL	ALL	ALL	ALL
GMC	Sierra EV	2026		ALL	ALL	ALL	ALL
GMC	Terrain	2026		ALL	ALL	ALL	ALL
GMC	Yukon	2026		ALL	ALL	ALL	ALL
GMC	Yukon XL	2026		ALL	ALL	ALL	ALL

Involved Region or Country	North America
Condition	Some customers may experience a condition where the Check Engine Light has illuminated and, in some cases, a Service Transmission Message is displayed on the DIC.
Cause	Engine Control Module (ECM) Internal Software for BEV applications Battery Energy Control Module (BECM).

Note: The Transmission Control Module (TCM) is not the cause of the P16F4 and it should not be replaced.

Correction

1. Turn vehicle off, open and close door, remove key from vehicle for 10 mins (Key Fob should be at least 50 feet from the vehicle)
2. Start vehicle

3. Attempt to shift to Drive, Reverse, Neutral, Park - if unable, repeat steps 1-3
 - i. If still unable, key off overnight
 - ii. If still unable to shift, follow Service Information Instructions
4. If vehicle shifts to Drive, Reverse, Neutral, and Park - key off, clear all DTCs
5. Key on, shift to Drive, Reverse, Neutral, Park
6. Check DTCs - if there is no DTC's set and the transmission engages drive and reverse, return vehicle to customer

If DTC P16F4 returns follow published Service Information.

Version	2
Modified	01/16/2026 Created on 01/28/2026 Changed repair information.

