

## Technical Service Bulletin (TSB)

### Clutch Switch Failure

|                    |                                                                                                                                                                                                                                                                                                                                                                                                  |       |                  |                                                                                                                                                                                                                                                                                                            |           |
|--------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| REFERENCE:         | TSB: 08-022-26<br>GROUP: 08 - Electrical                                                                                                                                                                                                                                                                                                                                                         | Date: | January 28, 2026 | REVISION:                                                                                                                                                                                                                                                                                                  | 08-393-25 |
| VEHICLES AFFECTED: | 2025 (JL) Jeep Wrangler<br>This bulletin applies to vehicles equipped with 6-Speed Manual Transmission (Sales Code DEM).                                                                                                                                                                                                                                                                         |       |                  | MARKET APPLICABILITY:<br><div><input checked="" type="checkbox"/> NA<input type="checkbox"/> MEA</div> <div><input type="checkbox"/> SA<input type="checkbox"/> IAP</div> <div><input type="checkbox"/> EE<input type="checkbox"/> CH</div><br><b>NOTE:</b> This bulletin applies to North America market. |           |
| CUSTOMER SYMPTOM:  | Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must set the following Diagnostic Trouble Code (DTC): <ul style="list-style-type: none"><li>P083F - Clutch Pedal Switch A/B Correlation.</li></ul> Customers may also experience the following: <ul style="list-style-type: none"><li>Vehicle no start.</li><li>Vehicle stop/start disabled.</li></ul> |       |                  |                                                                                                                                                                                                                                                                                                            |           |
| CAUSE:             | Clutch interlock switch electrical terminal corrosion                                                                                                                                                                                                                                                                                                                                            |       |                  |                                                                                                                                                                                                                                                                                                            |           |

This bulletin supersedes Technical Service Bulletin (TSB) 08-393-25, date of issue December 04, 2025, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include new Repair Summary and new Repair Procedure. Revisions that are not highlighted with **\*\*asterisks\*\*** include removal of the Inspection steps.

This Technical Service Bulletin (TSB) has also been released as a Rapid Service Update (RSU) 25-247, date of issue December 04, 2025. All applicable RSU VINs have been loaded. To verify this RSU service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.

#### REPAIR SUMMARY:

**\*\*This bulletin involves replacing the clutch interlock switch.\*\***

#### CLAIMS DATA:

| Labor Operation No: | Labor Description                                            | Skill Category                  | Labor Time |
|---------------------|--------------------------------------------------------------|---------------------------------|------------|
| 08-80-59-92         | Switch, Clutch Starter Interlock- Replace (1 - Semi Skilled) | 6 - Electrical and Body Systems | 0.4 Hrs.   |
| Failure Code        | ZY                                                           | Service Action                  |            |

**SPARE PARTS:**

| Qty    | Part No.   | Description                      | Notes |
|--------|------------|----------------------------------|-------|
| 1 (AR) | 68029261AA | Switch, Clutch Starter Interlock |       |

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.


If a customers VIN is listed in VIP or your RSU VIN list, perform the repair. If any vehicle not on the VIN list exhibits any of the symptom listed above in the customer symptom section, perform the Repair Procedure. **This bulletin applies only to vehicles on the RSU VIN list.**

**SPECIAL TOOLS/EQUIPMENT:**

| Description          | Ref. No. | Notes |
|----------------------|----------|-------|
| wiTECH or Equivalent | –        | –     |

**REPAIR PROCEDURE:**

1. \*\*Replace the Clutch Interlock Switch [Fig. 1](#). Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 06 - Clutch / Switch, Clutch Starter Interlock / Removal and Installation.



**Fig. 1**  
Clutch Starter Interlock Switch

1 - Clutch Starter Interlock Switch

2. Clean the clutch interlock switch electrical connector terminals using electrical contact cleaner and compressed air to remove any corrosion present.

3. Using wiTECH perform the Clutch Pedal Position Learn Procedure. This can be found under PCM > Misc. Functions tab.
4. Clear all DTC's before returning vehicle to customer.\*\*

**POLICY:**

Reimbursable within the provisions of the warranty.

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*