



Connection offline

Technical Service Bulletin

Transaction No.: **2078871/2**

45 Engine warning lamp (MIL) on - DTC U041800

Release date: Jan 30, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A5, S5, Q5, Q5 Sportback, SQ5, and SQ5 Sportback	2025 – 2026	All	Not applicable
A6 (FN)	2026		

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Added Model, MY)
1	08/01/2025	Initial publication

Customer states:

The engine warning lamp is/was on.

Workshop findings:

The customer's description is plausible. After a bus sleep cycle, the lamp may no longer be on, and the complaint may not be able to be reproduced in the workshop.

The DTC "U041800 ABS Control Module, implausible signal" is logged with symptom 487509 in diagnostic address 812C.

Technical Background

Signals from the ABS control unit are provided with a delay and trigger the warning lamp if the electrical system voltage is less than 12V.

Production Solution

Not applicable

Service

This service info aims to provide support during the repair. Please ensure a 12V power supply on the vehicle and delete the DTC above. The original customer complaint may have been resolved by a bus sleep cycle.

Please re-evaluate the vehicle based on the clear complaints.

The measures on how to correctly provide the signals and revise the warning messages are in development.

Warranty

This service info aims to provide support during work. Billing to this TSB number is not permitted.

Additional Information

All part and service references provided in this TSB (**2078871**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.