



Service Bulletin

Bulletin No.: PIP5865L

Date: February, 2026

PRELIMINARY INFORMATION

Subject: Diagnostic Tip: Malfunction Indicator Lamp (MIL) DTC P30BF That May Set As Current Or Failed In History On Vehicles With 5000 Miles Or Less

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT4-V	2020 - 2026		All	All	2.7 L3B	All
Chevrolet	Colorado	2023 - 2026		All	All	2.7 L3B and L2R	All
Chevrolet	Silverado 1500	2019 - 2026		All	All	2.7 L3B	All
GMC	Canyon	2023 - 2026		All	All	2.7 L3B and L2R	All
GMC	Sierra 1500	2019 - 2026		All	All	2.7 L3B	All

Involved Region or Country	North America
Condition	DTC P30C3, P30C7, P30CB or P30BF set as current or in history on vehicles with 5000 miles or less
Cause	Potential binding or sticking of the Intake/Exhaust camshaft sliding lobe pack

Correction

You may encounter one of the above listed vehicles that arrive in service with DTC P30C3, P30C7, P30CB or P30BF set as current or in history. If so, complete the following steps.

1. Clear DTC and allow full sleep cycle of vehicle. Open and close the driver's door. Wait for OnStar light to turn off and listen for relays in passenger footwell to click to indicate vehicle is asleep.
2. Start Vehicle and idle for 30 seconds and confirm no MIL
3. Drive vehicle, if MIL sets immediately upon moving the vehicle proceed to step 3a. If MIL does not set immediately proceed to step 4
 - a. Clear DTC and allow full sleep cycle of vehicle. Upon restarting the vehicle, perform a park rev to 4000 rpm for 15 seconds.
4. Drive at 23-25 mph for 10 minutes If no MIL is present, the issue is resolved.
 - a. If MIL resets at any time, return to step 1. Repeat process up to 4x." If codes return once completed proceed with the following.

Replace the profile actuator solenoids as follows:

P30BF, intake cylinders 1&2

P30C3, intake cylinders 3&4

P30C7, exhaust cylinder 2

P30CB, exhaust cylinder 3

If any of the above codes return then replace the Intake Camshaft and Roller followers (DTC P30BF, P30C3) or Exhaust Camshaft and Roller Followers (DTC P30C7, P30CB)

Clear remaining DTC's using GDS and evaluate the repairs.

If any of these codes return after the above repairs complete the published SI diagnostics for the related DTC's that have returned.

This PI may become a bulletin once additional information has been collected.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4082545	Diagnosis Profile Actuator Solenoids	0.4Hr
Add Time	Repeat Diagnosis Profile Actuator Solenoids	Up to 1.0 Hr.
Add Time Silverado/ Sierra/CT4	Intake/Exhaust Camshaft and Roller Follower replacement	4.7 Hr.
Add Time Colorado/ Canyon	Intake/Exhaust Camshaft and Roller Follower replacement	6.4 Hr.
Add Time Silverado/ Sierra	Camshaft Lobe Position Actuator Replacement	0.2Hr
Add Time Colorado/ Canyon	Camshaft Lobe Position Actuator Replacement	0.4Hr
Add Time CT4	Camshaft Lobe Position Actuator Replacement	0.2Hr
*This is a unique Labor Operation for Bulletin use only.		

Version	12
Modified	08/11/2022 - Created on. 01/13/2023 - Updated Model Year and correction. 03/06/2024 Updated Model Year and correction. 05/23/2024 - Updated Model Year and correction. 05/09/2025 - Updated Model Year. 07/28/2025 - Updated to include labor operation 08/15/2025 - Updated to include additional steps for clear related DTC 08/21/2025 - Updated to include 2026 Model Year. 09/08/2025- Updated labor operation 11/5/2025 - Updated and combined labor operations 01/29/2026 - Updated labor op for diagnose/swap profile actuator solenoids 02/11/2026 - Updated warranty section