



Connection offline

Technical Service Bulletin

Transaction No.: **2076356/5**

01 Engine control unit drive system faults P060C00 and U041600

Release date: Feb 24, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
Q5 (FY)	2022 – 2024	All	DMSA Engine
A4 (8W), A5 Sportback (F5)	2023 – 2024		

REVISION HISTORY		
Revision	Date	Purpose
5	-	Revised header (updated models) Revised condition (added to model table)
4	12/03/2025	Revised header (Updated models) Revised <i>Condition</i> (Added model table) Revised Service (Added models to SVM table)
3	04/25/2025	Revised <i>Warranty</i> (Updated labor operations)

Customer States:

- The EPC light is on.
- A drive system fault appears in the instrument cluster.

Workshop Findings:

The following event memory entries are logged in the engine control unit.

- **P060C00** – “Internal Control Module Main Processor Performance with DFCC 44160”.
- **U041600** – “Invalid Data Received from Vehicle Dynamics Control Module with DFCC 34193”.

Technical Background

Software issue with control unit.

Production Solution

New software in the Engine control module, -J623- (address word 0001) addressed the condition.

Service

To prevent charging of the high-voltage battery during the software update, the high-voltage cable is to be removed BEFORE the entry of the SVM code on vehicles with high-voltage components.

Charging the high-voltage battery during a software update can damage the high-voltage components.

1. Follow all instruction in TSB 2011732: *00 Software Version Management (SVM), operating instruction*.
2. Update the -J623- (0001) using the SVM action code as listed in the table below, if necessary:

Model	Old Software Part Number	Old Software Version	New Software Part Number (or higher)	New Software Version (or higher)	SVM Code Input
MY22 Q5	80A.907.115.B	0001 0002	80A.907.115.B	0003	01A267
MY23 Q5	80A.907.115.C	0001	80A.907.115.C	0002	01A267
MY24 Q5	80A.907.115.E	0001 0002	80A.907.115.E	0003	01A267
MY23 A4/A5	8W0.907.115.AM	0001	8W0.907.115.AM	0002	01A267
MY 24 A4/A5	8W0.907.115.AS	0001 0002	8W0.907.115.AS	0003	01A267

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0039		
Labor Operations:	Software Update	0151 0010	See SRT with associated operations
	Software Update	0151 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2076356/5		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

The engine control unit software must be updated on this vehicle. Inform the customer about the software update and ask them whether the engine control unit has been altered by chip tuning. Explain to the customer that updating the engine control unit software renders the chip tuning ineffective. In certain circumstances, the engine control unit may even be damaged by the software update. Ask the customer to clarify with the tuning company in advance whether a software update is possible. Damage to the engine control unit resulting from chip tuning cannot be billed to AUDI AG under warranty. Explain to the customer that neither AUDI AG nor your company can be held

responsible for damage caused by the software update or for damage that occurs as a result of not having the update performed. Make a note to this effect on the order before it is signed by the customer. Include this information in the customer file.

The engine control unit software must be updated on this vehicle. Explain to the customer that various control units must be reconfigured after the software update to ensure that they function correctly in conjunction with other control units in the vehicle. Components which have been retrofitted in the vehicle but have not been entered in the vehicle equipment list via feedback documentation (version compare) to the SVM may not function correctly after the configuration process. Ask the customer whether they have had non-genuine components retrofitted on the vehicle or modifications carried out by third parties (e.g. tuning) or are aware of any such retrofits or modifications. Inform the customer that, if non-genuine retrofits or modifications have been carried out on the vehicle by third parties, neither AUDI AG nor your own company will accept liability for any damage that may be caused by updating the software, or by failing to do so. Make a note to this effect on the order before it is signed by the customer. Include this information in the customer file.

All part and service references provided in this TSB (**2076356**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.