



TECHNICAL SERVICE BULLETIN

Gear Shift Module (GSM) Concerns

26-2066
24 February
2026

This bulletin supersedes 25-2579. Reason for update: update the symptoms in the TSB Issue, revise labor descriptions, and update the service procedure to clarify the usage of table 1 in step 4.

Model:

Ford 2021-2025 F-150	Built on or before 8-Sep-2025
--------------------------------	-------------------------------

Markets: North American markets only

Issue: Some of the vehicles listed in the Model statement above equipped with a console shift GSM may exhibit at least one of the following conditions:

- Clicking sound coming from the gear shift lever after it is placed and kept in R, N, or D position. (2024 only)
- Gear shift lever stuck in P
- Gear shift lever will not shift into P
- Gear shift lever will not shift out of gear
- Gear shift lever will not stow/unstow
- Gear shift lever will move past the P position
- Loose gear shift lever arm at pivot
- Illuminated powertrain malfunction (wrench) indicator with active DTCs P0929:77, P0929:00, P0929:07 and/or P0929:9A stored in the GSM

This may be due to the GSM.

NOTE: If the gear shift lever will not shift into park, the transmission will automatically engage into park when the return to park function is triggered.

Action: For vehicles that meet the criteria in the Issue and Model statements above, follow the Service Procedure to replace the GSM.

Parts

Service Part Number	Claim Quantity	Description
7210	1	Gear Shift Module - Refer To The Parts Catalog For The VIN Specific Application

Claim Quantity refers to the total number of individual pieces required to repair the vehicle. This may differ from the number of service part number packages due to the unit of issue (UOI).

As Needed indicates the part is necessary but amount of the part may vary and/or is not a whole number. Parts can be billed out as non-whole numbers, including less than 1.

Only If Necessary indicates the part is not mandatory. Refer to the Service Procedure to determine the inspection/inclusion criteria.

Warranty Status: Warranty coverage limits and policies are not altered by a TSB. Warranty coverage limits are determined by the identified causal part.

Labor Times

Description	Operation No.	Time

2021-2025 F-150 Console Shift With 10 Or 12 Inch Center Display Screen: Monitor PID And Verify Shifter Build Date (FAIL) Replace The GSM	262066A	0.9 Hrs
2021-2025 F-150 Console Shift With 10 Or 12 Inch Center Display Screen: Monitor PID And Verify Shifter Build Date (PASS)	262066B	0.3 Hrs
2022-2025 F-150 Console Shift With 15.5 Inch Center Display Screen: Monitor PID And Verify Shifter Build Date (FAIL) Replace The GSM	262066C	1.1 Hrs
2022-2025 F-150 Console Shift With 15.5 Inch Center Display Screen: Monitor PID And Verify Shifter Build Date (PASS)	262066D	0.3 Hrs
2021-2025 F-150: Extra Time To Release GSM Lever From Being Stuck In Stow Position (Can Be Claimed With Operation A Or C)	262066E	0.1 Hrs

Repair/Claim Coding

Causal Part:	7210
Condition Code:	42

Service Procedure

- With the system in Ready to Drive mode/engine running, apply and release the brake pedal while observing BRK_PDL_SW2 PID in the BCM. Does the BRK_PDL_SW2 PID change status when the brake pedal is pressed and released?
 - Yes - proceed to Step 2.
 - No - diagnose the brake pedal switch output and repair outside of this article. Refer to WSM, Section 307-05.
- Is the vehicle built on or before 08-Sep-2025?
 - Yes - proceed to Step 3.
 - No - this article does not apply. Refer to WSM, Section 307-05.
- Remove the left console trim to inspect the GSM build date. Refer to WSM, Section 501-12. (Figure 1)

Figure 1



- Verify the build date by using printed Julian date on the GSM. Refer to Table 1 and related bullet points.

Table 1

Example Serial Number							
1224085000200339							
1	2	24	085	000	20	03	39
Line	Shift	Calendar Year	Julian Date	Filler	Hour	Minute	Second

- Calendar Year "24"= 2024
- Julian Date "85"= 85th day of the calendar year 2024
- Use the Julian Date to determine the Build date of the GSM. 85th day of the calendar year 2024 is 25-Mar-2024. This example GSM was built on 25-Mar-2024.

5. Is the GSM built on or before 28-Aug-2025?

- (1). Yes - proceed to Step 6.
- (2). No - this article does not apply. Refer to WSM, Section 307-05 for normal diagnostics.

6. Replace the GSM. Refer to WSM, Section 307-05, which includes performing the PMI procedure to install the latest strategy files and carry out the TRON Module Authentication Procedure for 2024-2025 vehicles using the FDRS.

© 2026 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.