

REFERENCE:	TSB: 08-077-26 GROUP: 08 - Electrical	Date:	February 21, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 (DD) RAM 3500 Cab Chassis 2026 (DJ) RAM 2500 Pickup 2026 (DP) RAM 4500 / 5500 Cab Chassis 2026 (D2) RAM 3500 Pickup This bulletin applies to vehicles built on or before December 19, 2025 (MDH 1219XX) equipped with Selective Catalytic Reduction (UREA) (Sales Code XAL) and a 6.7L I6 Cummins HO Turbo Diesel Eng (Sales Code ETM).			MARKET APPLICABILITY: ☒ NA☐ MEA ☒ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to the North America and South America markets.	
CUSTOMER SYMPTOM:	Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs): • **P20BC-00 - Reductant Suction Line Heater Control Circuit High. - in Active or Stored status. • P202C-00 - Reductant Tank Heater Control Circuit High. - in Active or Stored status. • P20E8-00 - Reductant Pressure Too Low. - in Active or Stored status. • P209F-00 - Reductant Tank Heater Control Circuit Performance. - in Active or Stored status. • P208B-00 - Reductant Pump 1 Control Performance. - in Active or Stored status.** Customers may also comment one or more the following: • "Service Diesel Exhaust Fluid (DEF) System See Dealer" message in the Electronic Vehicle Information Center (EVIC). NOTE: This message will appear after the DEF pump fails to build pressure, a fault is set and the message continues to be displayed for 80 km (50 mi) of driving. • "Speed Will Be Limited To 8 kph (5 mph)" message displayed in the EVIC. CAUTION! If the vehicle is not taken to the dealership BEFORE reaching 241 km (150 mi) from when the "Service Diesel Exhaust Fluid (DEF) System See Dealer" message is displayed, the vehicles speed will be limited to 8 kph (5 mph). • Reduced acceleration from turbo.				
CAUSE:	DCU software				

REPAIR SUMMARY:

This bulletin reprogramming the DCU with the latest available software.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-18-9M	Unit, Def Control (DCU) - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
Failure Code	CC	Customer Concern	

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	-	-

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the DCU with the latest available software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

NOTE: For SA market only, after applying this TSB, it is not necessary to send DID-I or DID-A.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.