



Connection offline

Technical Service Bulletin

Transaction No.: **2067757/4**

01 "Drive system fault"/engine won't start- no DTC or P0191, P0087 - 5-cyl. 2.5 TFSI

Release date: Mar 20, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
TT RS	2020 – 2022	All	Not applicable
RS 3	2022 - 2024		

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised header (Updated software)
3	07/31/2023	Revised <i>Condition</i> (Updated Workshop findings)
2	01/03/2023	Revised header (Add MY23)

Customer states:

- The MIL light is illuminated.
- The drive system warning lamp light is on.
- The engine does not start.

Workshop findings:

No DTCs are stored, **OR** one of the following DTC entries is stored in the Engine Control Module, J623 (address word 0001):

- **P019100:** Fuel pressure sensor implausible signal with Symptom code: 5652, or with symptom 5653.
- **P008700:** Fuel Rail/System Pressure - Too Low with Symptom code: 2838.
- **P008800:** Fuel Rail/System Pressure - Too High with Symptom code: 2837, or with symptom 17897.

Technical Background

Diagnostic issue.

Production Solution

Not applicable.

Service

If Guided Fault Finding in ODIS yields no results for one of the DTC entries specified above, the test **G265 – “Intermediate Shaft Speed Sensor”** must also be performed.

If no test plan is suggested, please add the test manually to the test plan and work through it as specified in ODIS.



Try to reproduce the customer complaint (based on the description/cause of the issue), so that it can be clearly assigned to this TSB. The additional test must only be carried out if all the criteria (model/type, chassis number, engine/motor and gearbox code, PR number(s), part number, software version, code, etc.) apply exactly. Otherwise, this additional testing will not help to eliminate the problem and repeat testing may be necessary. In such a case, the warranty claim may be rejected.

Warranty

Claim Type:	If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	1366		
Damage Code:	0010		
Labor Operations:	Remove and install impulse sender.	2873 19xx	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol
	Charge Battery	2706 8950	See SRT with associated operations
Claim Comment:	As per TSB 2067757/4		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

Required Parts and Tools

Tool Number	Tool Description
VAS 6160/VAS 6150	VAS tester with the current version of ODIS (Windows 10)

Additional Information

All part and service references provided in this TSB (**2067757**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.