



Connection offline

## Vehicle-specific service

Transaction No.: **2081343/1**

93 PSS Q4 e-tron - Electrical drive system warning lamp DTC P0A2B00 (41505)

Release date: Mar 20, 2026

## Condition

| Model(s)                           | Year(s) | VIN Range | Vehicle Specific Equipment |
|------------------------------------|---------|-----------|----------------------------|
| Q4 e-tron, and Q4 Sportback e-tron | 2026    | All       | Not applicable             |

### Customer states:

- The electric drive system warning lamp is present in the cluster

### and/or

- The warning lamp for an active warning light is in the cluster

### and/or

- Various messages about the electric drive system are displayed in the cluster.

### Workshop findings:

- One or more of the customer statements can be reproduced.

The following DTC is stored (passive/intermittent or active/static) in the electric drive control unit (address word 0051):

- **P0A2B00:** Drive Motor “A” Temperature Sensor Circuit Range/Performance
  - Symptom: 41505

## Technical Background

Not applicable.

## Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

## Service

1. Diagnose the vehicle according to the instructions listed below. If the customer's vehicle condition matches the condition listed in the *Workshop Findings* of this PSS TSB, explain to the customer that the concern is currently under analysis, and an outcome is expected by the end of the second quarter 2026, subject to change. No repair is recommended at this time.
  2. Do not replace any components for this condition since this will not resolve the customer's concern.
  3. Create a PSS record in the PSS database via the Pending Service Solutions (PSS) link found in Audi Now; *Service* | *AU-US* > *Pending Service Solutions (PSS)*.
- 
1. Terminal 30 reset.

- Perform a terminal 30 reset according to the *Workshop Manual*.
2. Erase the DTC.
    - Use the vehicle diagnostic tester to erase the DTC P0A2B00 (with symptom 41505) under diagnostic address 0051.
  3. Perform an adaptation drive/road test (for drive motor rotor position).
    - Perform an adaptation drive/road test (for drive motor rotor position).
  4. Reassess the complaint after completing the adaptation drive/road test.
    - If the complaint **no longer** occurs, the measure ends here. The vehicle can be returned to the customer.
    - If the complaint **still** occurs, contact the Technical Assistance Center (TAC) and open a web ticket. Please include this TSB number (2081343) in the *Customer concern* field of your web ticket; this allows our TAC consultants to quickly refer to this bulletin. You will be contacted as soon as possible to provide further information.

## Warranty

|                          |                                                                                                                                                     |           |                                        |
|--------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|-----------|----------------------------------------|
| <b>Claim Type:</b>       | <ul style="list-style-type: none"> <li>If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.</li> </ul> |           |                                        |
| <b>Service Number:</b>   | 9318                                                                                                                                                |           |                                        |
| <b>Damage Code:</b>      | 0212                                                                                                                                                |           |                                        |
| <b>Labor Operations:</b> | Loosen and secure the grounding strap                                                                                                               | 9785 0950 | See SRT with associated operations     |
|                          | GFF/ Guided Functions                                                                                                                               | 0150 0010 | See SRT with associated operations     |
|                          | GFF/ Guided Functions                                                                                                                               | 0150 0060 | Time stated on the diagnostic protocol |
| <b>Claim Comment:</b>    | As per TSB 2081343/1                                                                                                                                |           |                                        |

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All part and service references provided in this TSB (**2081343**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.