

Technical Service Bulletin (TSB)
Flash: Central Vision Advanced Driver Assistance System (CVADAS) Module Update

REFERENCE:	TSB: 08-147-26 GROUP: 08 - Electrical	Date:	April 10, 2026	REVISION:	—
VEHICLES AFFECTED:	2026 (DT) RAM 1500 Pickup This bulletin applies to vehicles built on or before March 31, 2026 (MDH 0331XX) equipped with Trailer Reverse Steering Control (Sales Code XA1) or Surround View Camera System (Sales Code XAK).			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to the North America market.	
CUSTOMER SYMPTOM:	Customers must experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle must exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs): • B128E-92-PTS - Sensor-1-Performance Or Incorrect Operation. • B128F-92-PTS - Sensor-2-Performance Or Incorrect Operation. • B1290-92-PTS - Sensor-3-Performance Or Incorrect Operation. • B1291-92-PTS - Sensor-4-Performance Or Incorrect Operation. • B1292-92-PTS - Sensor-5-Performance Or Incorrect Operation. • B1293-92-PTS - Sensor-6-Performance Or Incorrect Operation. • B1294-92-PTS - Sensor-7-Performance Or Incorrect Operation. • B1295-92-PTS - Sensor-8-Performance Or Incorrect Operation. • B1296-92-PTS - Sensor-9-Performance Or Incorrect Operation. • B1297-92-PTS - Sensor-10-Performance Or Incorrect Operation. • B1298-92-PTS - Sensor-11-Performance Or Incorrect Operation. • B1299-92-PTS - Sensor-12-Performance Or Incorrect Operation. Customers may experience the following: • The Instrument Panel Cluster (IPC) displaying the following messages: ○ Service the park assist system. ○ Front and/or rear park assist is disabled.				
CAUSE:	CVADAS software				

REPAIR SUMMARY:

This bulletin involves reprogramming the CVADAS with the latest available software.

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-69-91	Module, Central Vision Advanced Driver Assistance System (CVADAS) - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.5 Hrs.
Failure Code	CC	Customer Concern	

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	-	-

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

1. Reprogram the CVADAS with the latest available software. If issues arise when flashing a module using the wiTECH Diagnostic Application, please submit a ticket to the Helpdesk. The helpdesk can be found within the Help menu.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.