



Service Bulletin

PRELIMINARY INFORMATION

Subject: Service Stability Traction ABS Rear Wheel Speed DTC Or Chassis Expansion Bus Communication Fault

Models: 2010 - 2012 Chevrolet Equinox

2010 - 2012 GMC Terrain

With Any Combination of DTCs U0073 U0074 U0125 C0196 C0287 C0186 C056D C0045 C0050 Symptom 00
06 3B 4A 4B 5A 39 42 54 71

This PI was superseded to add picture and diagnostic tips. Please discard PIT5171A.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern


Customers may comment on an intermittent DIC message Service Traction/Stability or ABS indicator. Upon diagnostics the technician may find DTCs related to the chassis bus, or rear wheel speed sensor with U0125 00 U0074 00 U0073 and or wheel speed sensor C0045 C0050 symptom 06 DTCs. Other DTCs U0125 U0126 C0196 5A C0710 5A may be related to an internal wire break inside the wire harness insulation to the X411 connector or possible unwanted rub through to ground. (Location in the left rear under the vehicle).

Recommendation/Instructions

Several conditions and symptoms have been found to be related to a wire harness at the left rear under vehicle. Inspect the wire harness insulation within 1 inch of the X411 before and after connector. It may be necessary to remove the tape and conduit from the wire harness for inspection upstream from the X411 connector. Some Issues have been found with circuits 6105 and 6106 for chassis bus wires and serial enable circuit 5986 and 120 ohm opens in 2500 and 2501 or 6106 and 6106. Other circuits 884, 885, 882, and 883 when related to rear wheel speed sensor codes C0045 or C0050. During inspection you may notice a discoloration in insulation in one spot of the wire. If you pull the wire near that area the insulation will break exposing the broken wire. Repair the circuit to complete the procedure.

Diagnostic tips on intermittent Chassis Buss and High Speed LAN Buss: Using DVOM set to Ohms, connect meter between DLC pins 12 and 13 for chassis buss or 6 and 14 for high speed buss of DLC connector, set the meter to Min / Max, and wiggle the harness up and down under the left-rear areas of the connector. When you hear the meter beeping, check that area of the harness.

Note: Wire broken within the insulation has also been found high up in the harness X411. Reference the following photos:



Warranty Information

For wiring repairs covered under warranty, please refer to latest version of bulletin 10-00-89-005 for warranty information on wire/connector repairs.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION