



Service Bulletin

PRELIMINARY INFORMATION

Subject: SES Lamp P0300 P0351 - P0358

Models: 2014 Chevrolet Silverado 1500

2014 GMC Sierra 1500

Built with RPOs 4.3L 5.3L L83 LV3

This PI was superseded to add a picture of the concern. Please discard PIP5147.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition/Concern

If the vehicle has a misfire with any of the following codes:

P0351-P0358, P2300, P2301, P2303, P2304, P2306, P2307, P2309, P2310, P2312, P2313, P2315, P2316, P2318, P2319, P2321, or P2322

Recommendation/Instructions

Inspect the coil connectors for a clear water and/or a discolored connector.

Picture of a coil with the concern:



If this is found inspect the pigtail for pin drag or loose terminals (repair as needed).

Swap the coil to a known good location.

If the concern follows the coil replace the coil or coils with the concern and add dielectric grease to the connection.

Warranty Information

For vehicles repaired under warranty use:

Labor Operation	Description	Labor Time
4020070	Ignition Coil Replacement	Use Published Labor Operation Time

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION