



# Service Bulletin

Bulletin No.: 20-NA-021  
Date: August, 2020

## TECHNICAL

Subject: Intermittent Service Steering Column Lock message displayed with U0155 Set

| Brand:    | Model:                     | Model Year: |      | Date Breakpoints : |                                                                                                        | Engine: | Transmission: |
|-----------|----------------------------|-------------|------|--------------------|--------------------------------------------------------------------------------------------------------|---------|---------------|
|           |                            | from        | to   | from               | to                                                                                                     |         |               |
| Chevrolet | Silverado 1500 (New Model) | 2019        | 2019 | SOP                | SILAO:<br>November 11, 2019<br><br>FORT WAYNE:<br>November 14, 2019<br><br>FLINT:<br>November 12, 2019 | All     | All           |
| Chevrolet | Silverado 1500             | 2020        | 2020 |                    |                                                                                                        |         |               |
| Chevrolet | Silverado 2500HD/3500HD    |             |      |                    |                                                                                                        |         |               |
| GMC       | Sierra 1500 (New Model)    | 2019        | 2019 |                    |                                                                                                        |         |               |
| GMC       | Sierra 1500                | 2020        | 2020 |                    |                                                                                                        |         |               |
| GMC       | Sierra 2500HD/3500HD       |             |      |                    |                                                                                                        |         |               |

|                            |                                                                                                                                                                                                                                                                                                                                                         |
|----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Involved Region or Country | United States, Canada, Mexico, Middle East and Israel.                                                                                                                                                                                                                                                                                                  |
| Additional Options (RPOs)  |                                                                                                                                                                                                                                                                                                                                                         |
| Condition                  | <p>Some customers may comment on a "Service Steering Column Lock" message displaying that may clear when the engine is started. A technician may find DTC U0155 set/stored in vehicles history.</p> <p>" DTC U0155: Lost Communication with Instrument Cluster</p>  |
| Cause                      | The cause of the condition may be the program in the Steering Column Lock Module is not optimized to the wake up signals on the communication bus.                                                                                                                                                                                                      |
| Correction                 | Reprogram the Steering Column Lock Module with the latest software, refer to K60 Steering Column Lock Module: Programming and Setup in SI.                                                                                                                                                                                                              |


5500772

## Service Procedure

**Caution:** Before downloading the update files, be sure the computer is connected to the internet through a network cable (hardwired). DO NOT DOWNLOAD or install the files wirelessly. If there is an interruption during programming, programming failure or control module damage may occur.

**Important:** Carefully read and follow the instructions below.


- " Ensure the programming tool is equipped with the latest software and is securely connected to the data link connector. If there is an interruption during programming, programming failure or control module damage may occur.
- " Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install a GM Authorized Programming Support Tool to maintain system voltage. Refer to [www.gmdesolutions.com](http://www.gmdesolutions.com) for further information. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.
- " Turn OFF or disable systems that may put a load on the vehicles battery such as; interior lights, exterior lights (including daytime running lights), HVAC, radio, etc.
- " Clear DTCs after programming is complete. Clearing powertrain DTCs will set the Inspection/Maintenance (I/M) system status indicators to NO.



5431207

Important: If the Same Calibration/Software Warning is noted on the SPS screen, select OK and follow screen instructions. After a successful programming event, the WCC is located in the Service Programming System dialogue box of the SPS Summary screen. No further action is required. Refer to the Warranty section of the bulletin.

1. Reprogram the Reprogram the Steering Column Lock Module. Refer to K60 Steering Column Lock Module: Programming and Setup in SI. Modify as required (e.g., select x module from the controller screen. Then provide step-by-step instructions or refer to SI procedure.



5431209

Important: To avoid warranty transaction rejections, you MUST record the warranty claim code provided on the SPS Warranty Claim Code (WCC) screen on the job card. Refer to callout 1 above for the location of the WCC on the SPS screen

2. Record SPS Warranty Claim Code on job card for warranty transaction submission.

Warranty Information

For vehicles repaired under warranty, use:

| Labor Operation | Description                                                | Labor Time                         |
|-----------------|------------------------------------------------------------|------------------------------------|
| *2810775        | Steering Column Lock Control Module Reprogramming with SPS | Use Published Labor Operation Time |

Important: \*To avoid warranty transaction rejections, carefully read and follow the instructions below:

" The SPS Warranty Claim Code must be accurately entered in the "SPS Warranty Claim Code" field of the transaction.

" When more than one Warranty Claim Code is generated for a programming event, it is required to document all Warranty Claim Codes in the "Correction" field on the job card. Dealers must also enter one of the codes in the "SPS Warranty Claim Code" field of the transaction, otherwise the transaction will reject. It is best practice to enter the FINAL code provided by SPS.

Warranty Claim Code Information Retrieval

If the SPS Warranty Claim Code was not recorded on the Job Card, the code can be retrieved in the SPS system as follows:

1. Open TIS on the computer used to program the vehicle.
2. Select and start SPS.

3. Select Settings.

4. Select the Warranty Claim Code tab.

The VIN, Warranty Claim Code and Date/Time will be listed on a roster of recent programming events. If the code is retrievable, dealers should resubmit the transaction making sure to include the code in the SPS Warranty Claim Code field.

|          |                                                                             |
|----------|-----------------------------------------------------------------------------|
| Version  | 2                                                                           |
| Modified | Released January 29, 2020<br>Revised July 29, 2020 – Added breakpoint dates |

