



Technical Service Bulletin

01 MIL on with hissing noise, DTC P227900 is stored in the ECM

01 21 95 2054795/2 January 12, 2021. Supersedes Technical Service Bulletin Group 01 number 19-15 dated April 23, 2019 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q8	2019 – 2020	All	Not Applicable
Q8	2021	000001 - 012624	Not Applicable
Q7	2020	All	Not Applicable
Q7	2021	000001 - 017214	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Updated models) Revised <i>Technical Background</i> (Updated) Revised <i>Production Solution</i> (Updated information) Revised <i>Service</i> (Updated information) Revised <i>Warranty</i> (Added table) Revised <i>Required Parts and Tools</i> (Added table)
1	04/23/2019	Initial publication

Customer states:

- MIL on.
- Hissing noise from the engine compartment during idle.

Workshop findings:

The following DTC is stored in the engine control module (ECM), J623 (address word 0001):

- **DTC P227900** (Intake Air System Leak).



Technical Service Bulletin

Technical Background

During assembly, the oil fill extension tube (Figure 1) may have been assembled incorrectly. If this extension tube is cross-threaded, an intake/vacuum leak may be generated at the interface between the extension tube and the valve cover (Figure 1, 7).




Figure 1. Oil fill extension tube (see possible cross-threading at number 7 on diagram).

Production Solution

To improve the assembly, the oil fill extension tube has been geometrically optimized and improvements in the assembly process were implemented.

Service

If an intake/vacuum leak is suspected, please inspect this component and verify proper sealing. If any components are damaged from cross threading, replace as necessary.



Technical Service Bulletin

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	1715		
Damage Code:	0050		
Labor Operations:	Oil fill tube removed + reinstalled	1715 1923	See SRT with associated operations
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 20 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2054795/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
06A103483D	Gasket	01
4M0115301K	Tube	01



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (2054795) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.