



TECHNICAL SERVICE BULLETIN

3.5L PowerBoost - Illuminated MIL With DTCs P2C23, P2601, P164C, And/Or P060B In The PCM - Built On Or Before 15-Feb-2021

**21-
2053**
02 March
2021

Model:

Ford 2021 F-150	Engine: 3.5L PowerBoost
---------------------------	-------------------------

Issue: Some 2021 F-150 vehicles equipped with a 3.5L PowerBoost engine and built on or before 15-Feb-2021 may experience an illuminated malfunction indicator lamp (MIL) with diagnostic trouble codes (DTC) P2C23, P2601, P164C, and/or P060B stored in the powertrain control module (PCM). This may be due to various software parameters within the PCM. To correct the condition, follow the Service Procedure to reprogram the PCM.

Action: Follow the Service Procedure steps to correct the condition if the vehicle meets all of the following criteria:

- 2021 F-150
- 3.5L PowerBoost engine
- Built on or before 15-Feb-2021
- Exhibits an illuminated MIL with DTCs P2C23, P2601, P164C, and/or P060B stored in the PCM

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Emissions Warranty/Service Part Warranty (SPW)/Special Service Part (SSP)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/Emissions Warranty/SPW/SSP/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2021 F-150 3.5L PowerBoost Retrieve DTCs And Reprogram The PCM (Do Not Use With Any Other Labor Operations)	212053A	0.3 Hrs.

Repair/Claim Coding

Causal Part:	RECALEM
Condition Code:	04

Service Procedure

1. Reprogram the PCM using the latest software level of the appropriate Ford diagnostic scan tool.

NOTE: Advise the customer this vehicle is equipped with an adaptive transmission shift strategy which allows the vehicle's computer to learn the transmission's unique parameters and improve shift quality. When the adaptive strategy is reset, the computer will begin a relearning process. This relearning process may result in firmer than normal upshifts and downshifts for several days.

© 2021 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.