



Preliminary Information

PIP5771B 8 Speed M5T MQE Transmission Setting DTC P0796

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2020 - 2021	All	All	All	M5T
Chevrolet	Silverado 1500	2020 - 2021	All	All	All	MQE
GMC	Canyon	2020 - 2021	All	All	All	M5T
GMC	Sierra 1500	2020 - 2021	All	All	All	MQE

Involved Region or Country	North America
Condition	Customer may comment that the Check Engine Light has illuminated the transmission is not shifting properly is slipping or has default to only one gear.
Cause	The technician may discover that DTC P0796 Transmission Control Solenoid Valve 3 Stuck Off has set. The DTC may be intermittent.

Correction:

The transmission oil pan should be removed and inspected.

If the pan is clean the control valve body should be replaced.

If there is evidence of failed clutch material the transmission should be removed inspected and a cost comparison should be completed to determine repair or replacement.

Any repair should include valve body replacement.

Version History

Version	3
Modified	12/17/2020 - Created on. 01/06/2021 - Removed RPO code MQC and added RPO code MQE. 03/02/2021 - Added the 2021 model year. Added the 2020-2021 Chevrolet Colorado and the 2020-2021 GMC Canyon. Added RPO M5T.



GENERAL MOTORS

© 2021 General Motors. All Rights Reserved.