

## **SSM 50071 - 2019-2021 Edge/Nautilus - Power Liftgate Inoperative From Both Switches**

Some 2019-2021 Edge/Nautilus vehicles may exhibit an inoperative power liftgate with or without diagnostic trouble code U3000:49 stored in the rear gate trunk module (RGTM). This may be due to the software in the RGTM. To correct the condition, reprogram the RGTM using the latest software level of the appropriate Ford diagnostic scan tool. For claiming use causal part 14B291 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.

### **APPLICABLE VEHICLES**

2019 - 2021 CAR: DQ CD539N EDGE

2019 - 2021 CAR: D9 U540N MKX