



Technical Service Bulletin

93 Red electrical malfunction warning, or the vehicle does not start, DTC U011000 is stored in the TCM

93 21 58 2065538/1 December 15, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A7 PHEV	2019 - 2021	All	PHEV
Q5 PHEV	2019 - 2021	All	PHEV

Condition

Customer states:

- There is a red electrical malfunction message or drive system malfunction in the instrument cluster.
- The vehicle does not start.

Workshop findings:

The following DTC may be stored in the transmission control module (TCM), J217 (address word 0002):

- **DTC U011000** (Lost Communication with Drive Motor Control Module 'A') active/static with symptom code 20952.

Technical Background

12 Volt supply briefly drops and a low-voltage monitoring system detects this. This can cause no further communication with the power electronics.

Production Solution

Not applicable.

Service

If the above conditions has been confirmed, proceed as follows:

1. Establish a full bus sleep cycle (leave vehicle stationary and locked for at least 20 minutes -> the time for a full bus sleep cycle may be longer or shorter, depending on the vehicle).
2. Erase the DTCs.
3. Establish a full bus sleep cycle.
4. Recheck for the concern.



Technical Service Bulletin

If the above does not repair the concern, then proceed with the ODIS test plans to repair the vehicle.



Tip: If it is deemed the 12 Volt battery is faulty, causing this concern the battery repair is not part of this TSB and should be performed in accordance to the *Audi Warranty Policies and Procedures Manual*.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9350		
Damage Code:	0040		
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	0121 0004	10 TU
Claim Comment:	As per TSB # 2065538/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2065538) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may



Technical Service Bulletin

these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.