



Technical Service Bulletin

87 Uncomfortable passenger compartment temperature

87 22 22 2066686/2 March 30, 2022. Supersedes Technical Service Bulletin Group 87 number 22-21 dated March 30, 2022, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2019 – 2021	All	Not Applicable
Q3	2022	000001 – 020297	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Condition</i> (updated verbiage for DTC)
1	03/30/2022	Initial publication

Customer states:

The customer complains that the air temperature in the cabin changes abruptly from the set temperature on the HVAC control. The rear air outlet in particular may lose the ability to adjust the outlet air temperature. It may only be capable of delivering full hot or full cold air.

Workshop findings:

While this symptom may be intermittent in nature it is still possible to duplicate this malfunction.

HVAC Electronics control module, E87 Control Module (address word 0008):

- DTC B131811: Potentiometer for rear vent temperature Short circuit to Ground (GND) may be stored in 08 - HVAC Electronics.

Technical Background



Technical Service Bulletin

The outlet air temperature sensor evaluation in the E87 HVAC control software can, in certain environmental conditions, cause irregular air temperature delivery among the available HVAC zones. Improved software is available to mitigate this symptom.

Production Solution

New software in the HVAC Electronics control module, E87 (address word 0008) has been implemented in production.

Service

SVM Update Instructions



Always use DoIP when flashing a control module via ODIS in supported vehicles.

To Activate DoIP, select *Administration>>General>>GFF Process>>DoIP communication>>Only allow DoIP communication*

This setting will automatically reset when the diagnostic session is ended.

You can tell if DoIP is active by observing a red LED on the VAS 6154(A)

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
2. Update the HVAC Electronics control module, E87 (address word 0008) using the SVM action code as listed in the table below, if necessary:

Model	Diagnostic Address	Old Software Part Number	Old Software Version	New Software Part Number (or higher)	New Software Version (or higher)	SVM Code Input
Q3	0008	83A820043*	0060	83A820043*	0070	08A035



Technical Service Bulletin

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles • G10 for CPO Covered Vehicles – Verify Owner • If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	8704		
Damage Code:	0039		
Labor Operations:	Software Update (Includes checking for DTCs)	0151 0000	Time stated on the diagnostic protocol (Max 30 TU)
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2066686/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2066686**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval



Technical Service Bulletin

system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.