



Technical Service Bulletin

45 DTC C1399F0 is stored in the ABS control module

45 22 24 2063679/3 May 20, 2022. Supersedes Technical Service Bulletin Group 45 number 21-19 dated July 23, 2021, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
e-tron GT, and RS e-tron GT	2022 – 2023	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised header (Added Model Year)
2	07/23/2021	Revised <i>Warranty</i> (Updated Claim Type)
1	06/16/2021	Initial publication

Customer states:

- Recuperation too low when braking on new vehicle.

Or

- After brake discs/brake pads have been replaced.

Workshop findings:

The following DTC may be stored in the ABS control module, J104 (address word 0003):

DTC C1399F0 (Brake application mode active).



Technical Service Bulletin

Technical Background

The brake application mode for breaking in the pad on the disc is being used for the first time at Audi.

This can be initiated with the Test Plan "003 Brake-In Service Pads".

At the same time, recuperation is deactivated and braking is performed manually. During this time, the specified DTC (C1399F0) is logged in the ABS control module, J104 (address word 0003).

The breaking-in process then takes place when the brakes are applied while driving. This is not shown actively to the customer in the instrument cluster or the MMI.

This mode and the DTC are deactivated automatically when the required amount of energy is reached, (for example: when the breaking-in process is complete).

Production Solution

Not applicable.

Service

If the brake discs and/or brake pads are replaced, or the DTC is present, proceed as follows:

- Select the following TEST Plan in ODIS (via GFF or Guided Functions): *003 Break-in service brakes*.
- Reevaluate the vehicle and release it afterward.

Warranty

Claim Type:	• 1EB up to 48 Months/50,000 Miles. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.
Service Number:	DADP



Technical Service Bulletin

Damage Code:	0010		
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
Claim Comment:	As per TSB 2063679/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2063679) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.