



Technical Service Bulletin

48 Red steering warning light is on, DTC C10AC07 is stored in the power steering control module

48 22 33 2064018/6 June 16, 2022. Supersedes Technical Service Bulletin Group 48 number 22-20 dated January 31, 2022, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, A8, Q5, SQ5, Q7, and Q8	2019 – 2022	All	Not Applicable
e-tron quattro	2019 2021 – 2022		
A6 allroad, S6, S8, e-tron Sportback quattro, SQ7, SQ8, and RS Q8	2020 – 2022		
A8 e quattro	2020 – 2021		
RS 6Avant, A7 e quattro, S7, RS 7, Q5 e quattro, Q5 Sportback, and SQ5 Sportback	2021 – 2022		

Condition

REVISION HISTORY



Technical Service Bulletin

Revision	Date	Purpose
6	-	Revised <i>Service</i> (Updated Note)
5	01/31/2022	Revised <i>Service</i> (Updated Note) Revised header (Added Model)
4	12/14/2021	Revised <i>Service</i> (Updated SVM Code and added Note)

Customer states:

- The red steering warning lamp lights up in the instrument cluster.
- The steering is heavy.

Workshop findings:

- The concern can be reproduced.

The following DTC is logged in the power steering control module, J500 (address word 0044):

- DTC C10AC07 (Steering Malfunction) with symptom code 5258760.



Note:

- Only proceed with the SVM update if the DTC C10AC07 is present in the J500.
- If there are other DTCs logged in the J500, proceed with GFF/test plans to resolve them.
- If the steering is heavy and there are no DTCs logged, proceed with a normal diagnosis.

Technical Background

The software for the power steering control module, J500 (address word 0044) needs to be updated.



Technical Service Bulletin

Production Solution

New software implemented in production.

Service

Proceed as follows:

1. Perform a visual check of the steering rack and steering boots, and verify if the steering wheel can be turned freely.
2. Check the "Control module temperature" value of address word 0044. The temperature should be >10°C at the live measurement after software update.

SVM Update Instructions

3. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions*.
4. Update the power steering control module, J500 (address word 0044) using the SVM action code 44A032 or (44A030 – See [TSB 2011732](#)) for parametrization of the control module.



Note:

- A. The software version will not change.
- B. Some specific hardware numbers may require the old SVM code 44A030.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner.
-------------	--



Technical Service Bulletin

	If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4835		
Damage Code:	0040		
Labor Operations:	Remove and install noise insulation	1082 1900	See SRT with associated operations
	Check steering rack for damage and free movement	4835 0199	20 TU
	Software Update (Includes checking for DTCs)	0151 0000	Time stated on the diagnostic protocol (Max 50 TU)
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2064018/6		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information



Technical Service Bulletin

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

- TSB 2011732: *00 Software Version Management (SVM), operating instructions.*

All part and service references provided in this TSB (2064018) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.