



Technical Service Bulletin

43 DTCs B200FF0, B200FF1, B200FF3, or B200FF4, B200FF5 stored in the J775 suspension control unit

43 22 65 2067531/1 July 12, 2022.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
----------	------	-----------	----------------------------



Technical Service Bulletin

A4, A4 allroad, and Q7	2017 – 2023	All	Not Applicable
A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, Q5, and SQ5	2018 – 2023		
RS 5	2018 – 2019 2021 – 2022		
RS 5 Sportback	2019 2021 – 2023		
S4, A6, A8, and Q8	2019 – 2023		
e-tron quattro	2019 2021 – 2023		
A8 e quattro	2020 – 2022		
A6 allroad, S6, A7, S7, S8, e-tron Sportback quattro, Q5 e- quattro, SQ7, SQ8, and RS Q8	2020 – 2023		



Technical Service Bulletin

RS 6 Avant, A7 e quattro, RS 7, Q5 Sportback, and SQ5 Sportback	2021 – 2023		
---	-------------	--	--

Condition

Customer states:

- Messages are shown in the instrument cluster: “Air suspension: system fault” or “Shock absorber system/suspension”.

Workshop findings:

One or more of the following DTCs are logged as static in the suspension control unit J775 (diagnostic address 0074):

- B200FF0: Internal malfunction
- B200FF1: Internal malfunction
- B200FF3: Internal malfunction
- B200FF4: Internal malfunction
- B200FF5: Internal malfunction

Technical Background

Not applicable.

Production Solution



Technical Service Bulletin

Not applicable.

Service

Perform the following steps:

1. Unplug the diagnostic connector from the vehicle.
2. Switch off the ignition.
3. Lock the vehicle (doors, hood and rear lid closed).
4. Wait until the vehicle has entered bus sleep mode.
5. Unlock the vehicle.
6. Plug the diagnostic connector into the vehicle.
7. Switch on the ignition.
8. Attempt to erase the DTCs.

If the DTCs in question are still logged as static, follow the instructions in Guided Fault Finding.

Warranty

Claim Type	• 110 Up to 48 Months/50,000 miles. • G10 for CPO Covered vehicles – Verify Owner. • Use applicable claim types. If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.
Service Number:	4316



Technical Service Bulletin

Damage Code:	0040		
Labor Operations:	Check vehicle (initiate bus sleep mode)	4316 0199	20 TU
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2067531/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2067531) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any



Technical Service Bulletin

form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.