



Technical Service Bulletin

87 Air Conditioning is inoperative, DTC B11AE15

87 22 32 2067362/2 September 20, 2022. Supersedes Technical Service Bulletin Group 97 number 22-84 dated June 22, 2022,
for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q8	2020 – 2023	All	Not Applicable
SQ8, and RS Q8	2021 - 2023		

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Required Parts and Tools</i> (updated part number for tape)
1	06/22/2022	Initial publication

Customer states:

- Customer states the A/C is inoperative and does not cool the vehicle.

Workshop findings:

The following DTC is stored in the onboard supply control unit J519 diagnostic address 0009.

- DTC B11AE15: A/C compressor regulator valve, open circuit/short circuit to B+.



Technical Service Bulletin

Technical Background

The wiring to the A/C compressor connector T3r is not long enough. Wires may become stretched, broken, or pulled from the connector as a result.

Production Solution

Harness length increased in production.

Service

If DTC B11AE15: A/C compressor regulator valve Open circuit/short circuit to B+ is stored in the onboard supply control unit J519 diagnostic address 0009, inspect the wiring at connector T3r in the area of the A/C compressor as seen in Figure 1.



Tip: It may be necessary to cut back the harness tape several inches to expose the damaged section of the harness.



Figure 1. N280 control wire damaged at T3r connection

If damage is found in this area, all 3 wires will need to be extended following the directions below.



Technical Service Bulletin

1. Cut back the damaged wire(s) until the wires are clean and free of any corrosion.
2. Extend all 3 wires so that a length of approximately 110mm is achieved when measuring from the base of the connector to the first branch in the harness. See Figure 2.
3. Ensure there is enough slack to keep the harness from stretching however not so much the wires hang down.
4. Repair and modify the harness using VAS 1978 B.
5. Wrap the harness section using fabric adhesive tape **N 105 920 02**.

Wrap wires up to 20mm from the base of the connector housing, as seen on the original harness in Figure 1.
6. Clear faults and perform a functional check.



Figure 2. Measure 110 mm from T3r to the first harness branch

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.
Service Number:	9712



Technical Service Bulletin

Damage Code:	0015		
Labor Operations:	Remove and install noise insulation	10 82 19 00	See SRT with associated operations
	Repair wiring harness	97 09 41 53	See SRT with associated operations
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2067362/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity



Technical Service Bulletin

See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
000 979 940	crimp connectors	03
000 979 025 E	individual wires	0.3 (only charge 2 wires from the pack of 5)
N 105 920 02	Fabric adhesive tape	0.2

Additional Information

All part and service references provided in this TSB (2067362) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.