



Technical Service Bulletin

19 Red coolant warning lamp on, DTCs P218100, P017B00, P017C00, and/or P017E00 are stored in the ECM

19 22 32 2062951/2 October 21, 2022. Supersedes Technical Service Bulletin Group 19 number 21-16 dated May 3, 2021, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8, S8	2019 – 2020	All	V8 TFSI
Q7, SQ7, Q8, SQ8, and RS Q8	2020	All	
RS 6 Avant, and RS 7 Avant	2021	900001 – 901935	
A8	2021	000001 – 007769	
S8	2021	000001 – 005379	
Q7, and SQ7	2021	000001 – 015609	
Q8, and SQ8	2021	000001 – 010457	
RS Q8	2021	000001 - 011352	

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>Warranty</i> (Updated Labor Ops)



Technical Service Bulletin

1	05/03/2021	Initial publication
---	------------	---------------------

Customer states:

- Red coolant warning lamp is illuminated in the instrument cluster.

Workshop findings:

The following DTCs may be stored in the engine control module (ECM), J623 (address word 0001):

- DTC P218100 (Malfunction in cooling system).
- DTC P017B00 (Cylinder head temperature sensor implausible signal).
- DTC P017C00 (Cylinder head temperature sensor short circuit to ground).
- DTC P017E00 (Cylinder head temperature sensor open circuit/loose contact).

Technical Background

Damage to the O-ring of the temperature sensor can cause water intrusion inside the plastic housing of the coolant temperature sender G407 (cylinder head temperature sensor). The moisture can damage the sensor element. The loss of function can be sporadic.

Production Solution

Improved part in production.

Service

1. Work through Guided Fault Finding.



Technical Service Bulletin

2. It is very important to also check whether the O-ring located directly on the tip of the coolant temperature sender G407 is visibly damaged and/or pinched (Figure 1).



Figure 1. O-ring is pinched.

3. Replace the G407 if it is damaged and/or pinched.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner.
-------------	--



Technical Service Bulletin

	If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	1978		
Damage Code:	0040		
Labor Operations:	Remove and install temperature sender	1978 19XX	See SRT with associated operations
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 20 TU)
	Road test prior to the service procedure	No Allowance	0 TU
	Road test after the service procedure	No Allowance	0 TU
Claim Comment:	As per TSB 2062951/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity



Technical Service Bulletin

See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
See ETKA	Coolant temperature sender G407	01

Tool Number	Tool Description
VAS 6160/VAS 6150	VAS tester with the current version of ODIS (Windows 10)

Additional Information

All parts and service references provided in this TSB (2062951) are subject to change and/or removal.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.