



Technical Service Bulletin

PSS 93 Electrical Malfunction Message Displayed on Start up, DTCs P060600 and P0A1B00 Stored in Electric drive 2
93 22 84 2068370/1 November 7, 2022.

Model(s)	Year	VIN Range	Vehicle Specific Equipment
Q4 e-tron quattro, and Q4 Sportback e-tron quattro	2022	All	Not Applicable
	2023	000001 - 000056	

Condition

Customer states:

- Intermittently at start-up driver receives a malfunction message in the instrument cluster "Electrical system malfunction! Please contact Service" (Figure 1).
- After a key cycle the vehicle operates normally.



Figure 1. A malfunction message is shown in the instrument cluster.

Workshop findings:



Technical Service Bulletin

The following DTCs are stored Electric drive 2 (DMC2), J944 (address word 00CE):

- DTC P060600: ECM/PCM Processor.
- DTC P0A1B00: Drive Motor "A" Control Module.

Technical Background

Software communication timing error on start-up.

Production Solution

Not applicable.

Service

If the above concern applies to the vehicle continue as follows:

Try to confirm the following:

- The warning is displayed on vehicle start-up.
- After an ignition cycle the vehicle operates normally.
- Clear the DTCs with the scan tool and confirm the vehicle drives normally on a test drive.

If the DTCs can be cleared and the vehicle drives normally the vehicle can be released to the customer.

Do not replace any parts as it will not fix the concern.

Explain to the customer that a solution for this concern is currently under investigation.



Technical Service Bulletin

Explain to the customer if the concern happens again they should turn the ignition off, wait a couple of seconds, and then turn the ignition back on. The vehicle will then operate normally.

Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under Related Links >> Service).

Warranty

Claim Type:	• Use applicable claim types. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9350		
Damage Code:	0039		
Diagnostic Time:	GFF – Checking and clearing faults	0151 0000	Time stated on the diagnostic protocol (Max 30 TU)
	Road test prior to service procedure	0121 0004	0 TU
	Road test after service procedure	No allowance	10 TU
Claim Comment:	As per TSB 2068370/1		

Additional Information



Technical Service Bulletin

All part and service references provided in this TSB (2068370) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.