



Technical Service Bulletin

PSS 93 Yellow warning lamp appears and/or the vehicle does not start, DTC P0A9500 is stored intermittently
93 22 86 2062953/3 November 10, 2022. Supersedes Technical Service Bulletin Group 93 number 22-65 dated February 8, 2022, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A8 e quattro, and Q5 e quattro	2020 – 2021	All	PHEV
A7 e quattro	2021 – 2022		

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised Header (Updated models)
2	02/08/2022	Revised Header (Corrected an Elsa display issue.)
1	04/14/2021	Initial publication

Customer states:

- The message “Electrical system: fault. Please contact workshop” (yellow warning lamp) appears in the instrument cluster.

And/or

- The vehicle does not start.

Workshop findings:



Technical Service Bulletin

The following DTC is intermittently stored in the hybrid battery regulation control module, J840 (address word 008C):

- DTC P0A9500 (High Voltage Fuse) with symptom code 28730.



Note:

According to Guided Fault Finding, the switching unit for the high-voltage battery should be replaced. However, replacing the part will **not** solve the problem.

Technical Background

During particularly dynamic cornering, it is possible that in rare, isolated cases, the DTC given above may be logged without a reason. This is caused by an irregularity in the diagnosis.

Production Solution

This bulletin will be updated when new information becomes available. New software that rectifies the irregularity in the diagnosis is currently in development.

Service

1. Explain to the customer that a solution is expected in the first quarter of 2023 and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).



Technical Service Bulletin

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9327		
Damage Code:	0040		
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 20 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2062953/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2062953**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.



Technical Service Bulletin

©2022 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.