



GROUP	MODEL
CHA	2021-2023MY Seltos (SP2)
NUMBER	DATE
117	December 2022

TECHNICAL SERVICE BULLETIN

SUBJECT: ABS/ESC LOGIC IMPROVEMENT FOR DTC C1626

This bulletin provides the procedure to update the software logic of the Anti-Lock Brakes/Electronic Stability Control (ABS/ESC) systems on some 2021-2023MY Seltos vehicles, which may experience multiple dash warning lights illuminated and DTC C1626, due to a possible yaw rate calculation error due to wheel alignment and tire diameter differences. This logic improvement will change the threshold sensitivity setting to account for these conditions. Follow the procedure outlined in this publication to apply the improved logic to the 'ABS/ESC' system using the KDS ECU Upgrade function as described in this bulletin. For confirmation that the latest reflash has been applied to a vehicle you are working on, verify the ROM ID using the table on page 3 of this bulletin.

DTC Description:

C162604 - Implausible Control



Kia Diagnostic System (KDS)

ECU Upgrade Procedure:

To correct this condition, the ECU should be reprogrammed using the KDS download, as described in this bulletin.

Upgrade Event Name
645. SP2 ABS/ESC MIL ON DTC (C1626) JUDGMENT LOGIC IMPROVEMENT

 NOTICE

- Confirm a fully charged battery (12.3 volts or higher is necessary) is used or utilize a fully charged jump starter box connected to the battery.
- **Ensure the KDS is sufficiently charged at 60% or higher prior to reflash.**
- All ECU upgrades must be performed with the ignition set to the 'ON' position unless otherwise stated.
- **Damaged VCI II units should not be used and promptly replaced.**
- Be careful not to disconnect the VCI-II connected to the vehicle during the ECU upgrade procedure.
- **DO NOT start the engine during ECU upgrade.**
- DO NOT turn the ignition key 'OFF' or interrupt the power supply during ECU upgrade.
- **When the ECU upgrade is completed, turn the ignition 'OFF' and wait 10 seconds before starting the engine.**
- ONLY use approved ECU upgrade software designated for the correct application.

 IMPORTANT

It is recommended to ALWAYS check the Electronic Parts Catalog (EPC) to locate the ECU Part Number respective to Auto/Manual Mode ROM IDs. DO NOT reference the parts label affixed to the ECU.

SUBJECT:

ABS/ESC LOGIC IMPROVEMENT FOR DTC C1626

 NOTICE

Before attempting an ECU upgrade on any Kia model, make sure to first determine whether the applicable model is equipped with an immobilizer  security system. Failure to follow proper procedures may cause the PCM to become inoperative after the upgrade and any claims associated with this repair may be subject to chargeback.

ROM ID INFORMATION TABLE:

Upgrade Event #645

Model	System	ECU P/No.	ROM ID	
			Previous	New
Seltos (SP2)	ABS/ESC	58910 Q5100	1.00 1.01	1.02
		58910 Q5200	1.00 1.01	1.02
		58910 Q5300	1.00 1.01	1.02
		58910 Q5400	1.00 1.01	1.02
		58910 Q5450	1.00 1.01	1.02

To verify the vehicle is affected, be sure to check the Calibration Identification of the vehicle's ECM ROM ID and reference the Information Table as necessary.

NOTICE

Prior to performing the ECU upgrade, be sure to check that the KDS is fully charged.

1. Connect the VCI-II to the OBD-II connector, located under the driver's side of the instrument panel.

NOTICE


The ECU upgrade function on KDS operates wirelessly. It is not necessary to perform the upgrade via USB cable.




2. With the ignition ON, turn ON the KDS tablet. Select 'KDS' from the home screen.



3. Confirm communication with VCI (A) and then configure the vehicle (B) using the 'AUTO VIN' (C) feature.



4. Select 'ECU Upgrade'.




SUBJECT:

ABS/ESC LOGIC IMPROVEMENT FOR DTC C1626

5. The KDS will check the server for recently uploaded Events and then automatically download Upgrade Event #645.

NOTICE

The vehicle must be identified in Vehicle Selection to download an Event for that vehicle.




6. Select Auto Mode.

CAUTION

Do NOT attempt to perform a Manual Mode upgrade UNLESS Auto Mode fails. Always follow the instructions given on the KDS in either Auto or Manual mode.




7. Select the ABS/ESC system under the System selection menu.
- Touch ID Check (D) and confirm that the latest update is available.
- Select Upgrade Event #645, and select Upgrade to continue.



8. The ECU upgrade will begin and the progress of the upgrade will appear on the bar graph.
- Upgrade part (1/2) (E) will download the upgrade event to the VCI-II. Upgrade part (2/2) (F) will upgrade the ECU.

CAUTION


Do not touch the system buttons (like 'Back', 'Home', 'etc.') while performing ECU Upgrade.




9. If a "Communication Fail" screen appears, verify that the VCI-II and KDS are communicating properly. Select 'OK' and restart the from step 4.

NOTICE


If an error notice continues to appear or if the upgrade cannot be performed, DO NOT disconnect the KDS/VCI-II. Contact GIT America Help Desk at (888) 542-4371 or Techline.




10. When instructed on the KDS, turn the ignition OFF for ten (10) seconds then back on. Select 'OK' to continue.



11. Once the upgrade is complete, select 'OK' to finalize the procedure.



12. When prompted, select 'YES' to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.



13. Start the engine to confirm normal operation of the vehicle.

Manual Upgrade Procedure:

 NOTICE

The manual upgrade should **ONLY** be performed if the automatic upgrade fails.

If the automatic upgrade fails, turn the ignition 'OFF' for about 10 seconds then place it back in the 'ON' position to reset the control unit BEFORE performing manual upgrade.

See table below for 'Manual Mode' passwords.

Manual Mode ECU Upgrade Passwords

Menu	Password
SP2 ABS/ESC : 58910-Q5100	5100
SP2 ABS/ESC : 58910-Q5200	5200
SP2 ABS/ESC : 58910-Q5300	5300
SP2 ABS/ESC : 58910-Q5400	5400
SP2 ABS/ESC : 58910-Q5450	5450

1. Within the ECU Upgrade screen displayed, select **Manual Mode**.
2. Select the ABS/ESC system under the System selection menu. Select **Upgrade Event #645** and select **Upgrade** to continue.
3. Select the appropriate control unit part number with reference to the ROM ID Information Table on page 3, and select **OK**.
4. Enter the appropriate password from the Manual Mode password table above and select **OK**.
5. The upgrade will begin and the progress of the upgrade will appear on the bar graph.
6. When instructed on the KDS, turn the ignition **OFF** for ten (10) seconds then back on. Select **OK**.
7. Once the upgrade is complete, select **OK** to finalize the procedure.
8. When prompted, select **YES** to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.
9. Start the engine to confirm proper operation of the vehicle.

SUBJECT:

ABS/ESC LOGIC IMPROVEMENT FOR DTC C1626**AFFECTED VEHICLE RANGE:**

Model	Production Date Range
Seltos (SP2)	2021 - 2023MY

REQUIRED TOOL:

Tool Name	Figure	Comments
KDS		Kia Diagnostic System

WARRANTY INFORMATION:**N Code: I3A C Code: ZZ3**

Model	Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
SP2	W	58910 Q5100	0	ABS/ESC Logic Improvement	58910F11	0.3 M/H	N/A	0