



GROUP

MODEL

ELE

2023MY
Niro EV (SG2 EV)

NUMBER

DATE

280

January 2023

TECHNICAL SERVICE BULLETIN

SERVICE ACTION: EV BATTERY COOLANT
AIR BLEEDING PROCEDURE (SA522)

SUBJECT:

This bulletin provides information to perform the 'Battery EWP Operation Mode for Degassing and Circulation' (battery coolant air bleeding procedure) on the Battery Management System (BMS) for some 2023MY Niro EV (SG2 EV) vehicles produced from July 11, 2022 through November 20, 2022, which may have inadvertent air trapped inside of the coolant line due to BMS software logic error of the heater relay, which may generate an MIL 'ON' with DTC P1BA800 stored. Kia is requesting the completion of this Service Action on all affected vehicles in dealer stock, prior to delivery. Follow the procedure outlined in this publication to perform the air bleeding procedure on the battery coolant line. Before conducting the procedure, verify that the vehicle is included in the list of affected VINs.

DTC Description:

P1BA800 : Heater Relay Fault



Kia Diagnostic System (KDS)

NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA522.


A printed copy is for reference only; publication information can be updated at any time.
Always refer to KGIS for the latest information. After logging in kdealer.com, the newest technical publications are listed in 'Service Releases' and has the latest service information that has been released.

Repair Procedure:


1. Open the hood.




2. Open the front trunk (A).



3. Remove the service cover (B).



4. Open the auxiliary 12V battery positive (+) terminal cover (C).



5. Confirm a fully charged battery (12.3 volts or higher is necessary) is used and utilize a fully charged jump starter box connected to the battery.

SUBJECT SERVICE ACTION: EV BATTERY COOLANT AIR BLEEDING PROCEDURE (SA522)


6. Attach a small strip of no-residue tape on the coolant reservoir to mark the current coolant level.



7. Connect the VCI-II to the OBD-II connector, located under the driver's side of the instrument panel.



- 8a. Verify DTC P1BA800 is not stored.
- 8b. If stored, clear the DTC.
9. From the Home screen on KDS, select 'Actuation Test'.




SUBJECT: SERVICE ACTION: EV BATTERY COOLANT AIR BLEEDING PROCEDURE (SA522)

10. Select 'BMS' System.
11. Select 'OK'.




12. Select 'Battery EWP Operation Mode for Degassing and Circulation'.

Note: Electric Water Pump (EWP)




13. Select 'Start' to begin test.

Note: Allow the EWP operation to run for twenty (20) minutes.



SUBJECT SERVICE ACTION: EV BATTERY COOLANT AIR BLEEDING PROCEDURE (SA522)


14. Select 'Stop' after 20 minutes of operation.



The screenshot shows a 'Data Analysis' window with a table of sensor data. The 'Stop' button in the top navigation bar is highlighted with a red dashed box. The table lists various sensors and their current values and units.

Sensor Name(427)	Value	Unit
BMS EWP#1 Operation RPM Request	3100	RPM
EWP#1 Operation RPM	3080	RPM
Battery Module 16 Temperature	16	°C
Battery WCS Inlet Temperature	17	°C
Battery LTR Rear Temperature	17	°C
BMS Radiator FAN Operation Duty Request	0	%
Radiator FAN Operation Duty Feedback	0	%

15. Inspect the coolant level. If coolant level is lower than the tape marking, refill coolant level to the 'MAX' line.



16. Reinstall all removed parts in the reverse order of removal.
17. Verify normal vehicle operation.

SUBJECT: SERVICE ACTION: EV BATTERY COOLANT AIR BLEEDING PROCEDURE (SA522)**AFFECTED VEHICLE RANGE:**

Model	Production Date Range
Niro EV (SG2 EV)	July 11, 2022 to November 20, 2022

REQUIRED TOOL:

Tool Name	Figure	Comments
'No Residue' Tape		Locally Sourced
KDS		Kia Diagnostic System

REQUIRED PART:

Part Name	Part Number	Figure	Qty.
Coolant	UM020 CH237		As needed to top off

WARRANTY INFORMATION:**N Code: N99 C Code: C99**

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
V	37501 CV051	0	(SA522) Battery Coolant Air Bleeding + Refill (DTC P1BA800 Stored)	220145R0	0.5 M/H	N/A	0
			(SA522) Battery Coolant Air Bleeding + Refill (No DTC P1BA800 Stored)	220145R1	0.5 M/H	N/A	0

Note: For coolant top off and locally sourced 'no residue' tape, use sublet code 'X1' with a maximum allowed amount of \$9.70 per vehicle to complete ELE280/SA522.

NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference **SA522** when accessing the WebDCS system.