

# Technical Service Bulletin



**PSS 01 - MIL / EPC light on, various warnings or poor performance - P060C00 stored in ECM - V6 TFSI**  
01 23 33 2067767/2 January 3, 2023. Supersedes Technical Service Bulletin Group 01 number 22-23 dated August 11, 2022 for reasons listed below.

| Model(s) | Year        | VIN Range | Vehicle-Specific Equipment |
|----------|-------------|-----------|----------------------------|
| Q7       | 2020 – 2022 | All       | 3.0 L V6                   |
| Q8       | 2019 – 2022 |           |                            |

## Condition

| REVISION HISTORY |            |                                 |
|------------------|------------|---------------------------------|
| Revision         | Date       | Purpose                         |
| 2                | -          | Revised header (Updated Models) |
| 1                | 08/11/2022 | Initial publication             |

### Customer States:

- Various warning lamps are on in the instrument cluster (including MIL and/or EPC warning lamps).
- Poor performance.

### Workshop Findings:

The following DTC is stored in the ECM, J623 (address word 0001):

- **P060C00:** Control module internal system fault **with symptom 30924**.

## Technical Background

There is a discrepancy in the engine control unit software.

## Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

## Service

**Please postpone repairs as there is currently no effective repair for the complaint described by the customer.**



1. Explain to the customer that a solution is being developed and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> *Service*), or through the Technical Assistance page in Elsa.

## Warranty

This TSB is informational only and not applicable to any Audi warranty.

## Additional Information

All parts and service references provided in this TSB (**2067767**) are subject to change and/or removal.  
©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.