



Preliminary Information

PIP5843B Information on Malfunction Indicator Lamp (MIL) Illuminated with DTCs P30C3 P30BF P30C7 Or P30CB Setting As Current Or History

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	CT4	2020 - 2023	All	All	2.7L (L3B)	All
Chevrolet	Silverado 1500 (New Model)	2019 - 2023	All	All	2.7L (L3B)	All
GMC	Sierra 1500 (New Model)	2019 - 2023	All	All	2.7L (L3B)	All

Involved Region or Country	North America
Condition	Malfunction Indicator Lamp (MIL) Illuminated with one or more of the following DTCs P30C3, P30BF, P30C7, or P30CB setting as current or in history
Cause	Potential Intake Camshaft sliding lobe pack binding or sticking

Correction:

NOTE: This issue is more likely to occur below 10,000 Miles / 16,000 Kilometers.

One of the above listed vehicles may arrive in service with the complaint of Malfunction Indicator Lamp (MIL) Illuminated with one or more of the following DTCs P30C3, P30BF, P30C7, or P30CB stored as current or in history.

Perform the SI electrical diagnostics for the associated codes.

If no trouble is found in the lobe position sensors or wiring, proceed to replace the cam lobe actuators as follows:

P30BF, intake cylinders 1&2

P30C3, intake cylinders 3&4

P30C7, exhaust cylinder 2

P30CB, exhaust cylinder 3

If actuators have previously been replaced and the fault returns, replace the intake camshaft (P30BF or P30C3) or exhaust camshaft (P30C7 or P30CB).

Note: The Intake and Exhaust Cam Profile Actuator Solenoids are not interchangeable with each other

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4088848	Swapping of Cam Profile Actuators and Wiring/Terminal Testing or Inspection	0.4 Hr.
*This is a unique Labor Operation for Bulletin use only.		

Version History

Version	3
Modified	03/03/2022 - Created on. 12/05/2022- Updated to include Unique Labor Op, diagnostic direction and replace Intake Camshaft if needed. 01/13/2023- Updated to include 23MY and remove reference to cold ambient temperatures



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.