



Bulletin No.: PIP5899
Published date: 01/31/2023

Preliminary Information

PIP5899 DTC P0F39 - Hybrid/Electric Vehicle Coolant Heater Current Sensor Circuit Low

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Lyriq	2023 - 2023	All	All	ENO	All

Involved Region or Country	North America
Condition	Some customers may observe a Malfunction Indicator Lamp (MIL) caused by DTC P0F39 - Hybrid/Electric Vehicle Coolant Heater Current Sensor Circuit Low.
Cause	A software anomaly has been identified in the BECM module which may falsely set this DTC.

Correction:

Reprogram the K16 Battery Energy Control Module to correct the condition.

Please do not replace the E54V Hybrid/Electric Vehicle Coolant Heater, unless the BECM has been programmed on a previous repair attempt.

Warranty Information

Labor Operation	Description	Labor Time
2810945	Battery Energy Control Module Reprogramming with SPS	Use Published labor Time

Version History

Version	1
Modified	1-31-2023 - Created



© 2023 General Motors. All Rights Reserved.