

Technical Service Bulletin



43 DTCs B200FF0, B200FF1, B200FF3, or B200FF4, B200FF5 stored in the J775 suspension control unit
43 23 72 2067531/2 May 19, 2023. Supersedes Technical Service Bulletin Group 43 number 22-65 dated July 12, 2022, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4 allroad, A4, and Q7	2017 – 2024	All	Not Applicable
S4, Q5, and SQ5	2018 – 2024		
A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, A6, A7, A8, and Q8	2019 – 2024		
RS 5, RS 5 Sportback, and e-tron quattro	2019 2021 – 2024		
A6 allroad, S6, S7, S8, e-tron Sportback quattro, SQ7, SQ8, and RS Q8	2020 – 2024		
A8 e quattro	2020 – 2021		
RS 6 Avant, RS 7, Q5 e quattro, Q5 Sportback, and SQ 5 Sportback	2021 – 2024		
A7 e quattro	2021 – 2022		
e-tron S quattro	2022 - 2024		

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised <i>header</i> (Added Model Year)
1	07/12/2022	Initial publication

**Customer states:**

- Messages are shown in the instrument cluster: “Air suspension: system fault” or “Shock absorber system/suspension”.

Workshop findings:

One or more of the following DTCs are logged as static in the suspension control unit J775 (diagnostic address 0074):

- B200FF0: Internal malfunction.
- B200FF1: Internal malfunction.
- B200FF3: Internal malfunction.
- B200FF4: Internal malfunction.
- B200FF5: Internal malfunction.

Technical Background

Not Applicable

Production Solution

Not Applicable

Service

Perform the following steps:

1. Unplug the diagnostic connector from the vehicle.
2. Switch off the ignition.
3. Lock the vehicle (doors, hood and rear lid closed).
4. Wait until the vehicle has entered bus sleep mode.
5. Unlock the vehicle.
6. Plug the diagnostic connector into the vehicle.
7. Switch on the ignition.
8. Attempt to erase the DTCs.

If the DTCs in question are still logged as static, follow the instructions in Guided Fault Finding.

Warranty

Technical Service Bulletin



Claim Type	• 110 Up to 48 Months/50,000 miles. • G10 for CPO Covered vehicles – Verify Owner. • Use applicable claim types. If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4316		
Damage Code:	0040		
Labor Operations:	Check vehicle (initiate bus sleep mode)	0689 0199	20 TU
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2067531/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2067531**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.