

Technical Service Bulletin (TSB)

Flash: Transmission Control Module (TCM) Updates

REFERENCE:	TSB: 21-010-23 GROUP 21 - Transmission and Transfer Case	Date:	April 14, 2023	REVISION:	–
VEHICLES AFFECTED:	2022 (GA) Alfa Romeo Giulia This bulletin applies to vehicles equipped with a 2.9L V6 Twin-Turbo PDI Engine W/ESS (Sales Code EEC) with an 8-Speed Automatic 8HP75 Transmission (Sales Code DFV).			MARKET APPLICABILITY: ☒ NA ☐ MEA ☒ SA ☐ IAP ☐ EE ☐ CH	
CUSTOMER SYMPTOM:	Customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find the following Diagnostic Trouble Codes (DTCs) have been set: • P043E-00 - EVAP System Leak Detection Reference Orifice Low Flow. • P2C33-00 - Crankcase Pressure Sensor B Circuit Range/Performance. • P2C91 - Crankcase Ventilation System - Hose "B" Disconnected. • P00B2-00 - Radiator Coolant Temperature Sensor Circuit Range-Performance. • P304A-00 - Fuel Rail Pressure Sensor 1 - Out Of Range High. • P304E-00 - Fuel Rail Pressure Sensor 2-Out Of Range High. • P02D2-00 - Cylinder 4 Fuel Injector "A" Offset Learning At Min Limit. • P0607-00 - Control Module Performance. • P0072-00 - Ambient Air Temperature Sensor Circuit Low. • P0073-00 - Ambient Air Temperature Sensor Circuit High.				
CAUSE:	TCM Software				

REPAIR SUMMARY:

This bulletin involves reprogramming the TCM with the latest available software.

NOTE: Additional module flash is required for this update to be effective, the following module is to be updated along with this TCM update:

- Powertrain Control Module (PCM).

CLAIMS DATA:

Labor Operation No:	Labor Description	Skill Category	Labor Time
18-19-05-RW	Module, Transmission Control (TCM) - Reprogram (0 - Introduction)	2 - Automatic Transmission	0.2 Hrs.
Failure code	CC	Customer Concern	

The dealer must use failure code CC with this Technical Service Bulletin.

- If the customer's concern matches the SYMPTOM identified in the Technical Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Technical Service Bulletin flash/reprogramming conditions.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the one listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptoms listed above in the customer symptom section, perform the Repair Procedure.

SPECIAL TOOLS/EQUIPMENT:

Description	Ref. No.	Notes
wiTECH or Equivalent	—	—

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

NOTE: The PCM must be updated to the latest available software at the conclusion of this repair procedure. Refer to all applicable published technical service bulletins for detailed repair procedures and labor times regarding updating the PCM software.

CAUTION! Failure to update the PCM module following an TCM software update may result in vehicle malfunctions.

1. Reprogram the TCM with the latest available software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Verify the PCM is also programmed with the latest available software. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the PCM software.
3. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.