



Technical Service Bulletin

01 Drive system fault OR no engine start - P019100, P008700, P008800 - 5-cyl. TFSI

01 23 65 2067757/3 July 31, 2023. Supersedes Technical Service Bulletin Group 01 number 23-32 dated January 3, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
RS 3	2017 – 2020 2022 – 2023	All	Not Applicable
TT RS	2018 – 2022	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised <i>Condition</i> (Updated Workshop findings)
2	01/03/2023	Revised header (Add MY23)
1	08/23/2022	Initial publication

Customer states:

- The MIL light is illuminated.
- The drive system warning lamp light is on.
- The engine does not start.

Workshop findings:

No DTCs are stored, **OR** one of the following DTC and symptom code combinations are stored in the Engine Control Module, J623 (address word 0001):

- **P019100**: Fuel pressure sensor implausible signal with Symptom code: 5652, or with symptom 5653.
- **P008700**: Fuel Rail/System Pressure - Too Low with Symptom code: 2838.
- **P008800**: Fuel Rail/System Pressure - Too High with Symptom code: 2837, or with symptom 17897.

Technical Background

Not applicable.

Production Solution

Not applicable.



Technical Service Bulletin

Service

If Guided Fault Finding in ODIS yields no results for one of the DTC entries specified above, the test **G265 – “Intermediate Shaft Speed Sensor”** must also be performed.

Please add the test manually to the test plan and work through it as specified in ODIS.



Try to reproduce the customer complaint (based on the description/cause of the issue), so that it can be clearly assigned to this TSB. The additional test must only be carried out if all the criteria (model/type, chassis number, engine/motor and gearbox code, PR number(s), part number, software version, code, etc.) apply exactly. Otherwise, this additional testing will not help to eliminate the problem, and repeat testing may be necessary. In such a case, the warranty claim may be rejected.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	1366		
Damage Code:	0010		
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Remove and install impulse sender.	2873 1930	70 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2067757/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Tool Number	Tool Description
VAS 6160/VAS 6150	VAS tester with the current version of ODIS (Windows 10)



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (**2067757**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.