



Technical Service Bulletin

01 Drive system fault - P060C00 - 2.0 ltr. 4-cyl. TFSI

01 23 70 2071242/1 August 18, 2023.]

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5 e quattro	2020 – 2021	All	Not Applicable
A7 e quattro	2021 – 2022		

Condition

Customer states:

- A fault is indicated in instrument cluster.
- Vehicle has reduced power.

Workshop findings:

The following DTC and symptom code combinations are stored in the Engine Control Module, J623 (address word 0001):

- **P060C00** "Internal Control Module Main Processor Performance" is stored in the diagnostic log with symptom 32328.

Technical Background

The software for the TCM control module, J217 (address word 0002) needs to be updated.

Production Solution

New software in the Transmission control module, J217 (address word 0002) addressed the condition.

Service



Always use DoIP when flashing a control module via ODIS in supported vehicles.

To Activate DoIP, select *Administration>>General>>GFF Process>>DoIP communication>>Only allow DoIP communication*

This setting will automatically reset when the diagnostic session is ended.

You can tell if DoIP is active by observing a red LED on the VAS 6154(A)

1. Follow all instructions in TSB 2011732: *00 Software Version Management (SVM), operating instructions.*



Technical Service Bulletin

2. Update the TCM (J217) using the SVM action code as listed in the table below, if necessary:

Model	ECM	TCM Old Software Part Number	TCM Old Software Version (or lower)	TCM New Software Part Number (or higher)	TCM New Software Version (or higher)	SVM Code Input
Q5	80A.906.259.B	80A.927.156.C	0004	80A.927.156.C	0005	02A220
Q5	80A.906.259.C	80A.927.156.D	0002	80A.927.156.D	0003	02A220
A7	4K0.906.259.L	4K0.927.156.D	0001	4K0.927.156.D	0002	02A220

Warranty

Claim Type:	110 up to 48 Months/50,000 Miles. - G10 for CPO Covered Vehicles – Verify Owner. - If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0039		
Labor Operations:	Software Update (Includes checking for DTCs)	0151 0000	Time stated on the diagnostic protocol (Max 50 TU)
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No Allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2071242/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Tool Number	Tool Description
VAS 6160/VAS 6150	VAS tester with the current version of ODIS (Windows 10)



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (**2071242**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.