



Technical Service Bulletin

01 PSS ECM "Drive system: fault" - P060C00 Internal Control Module Performance 4-cyl. 2.0 ltr. TFSI
01 23 84 2070571/2 October 16, 2023. Supersedes Technical Service Bulletin Group 01 number 23-58 dated June 9, 2023, for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A4, A4 allroad, A5, A5 Cabriolet, A5 Sportback, Q5, Q5 e quattro, and Q5 Sportback	2022 – 2023	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Add Model Year, Models)
1	06/09/2023	Initial publication

This bulletin applies to **A4/A5/Q5 Model Years 2022 – 2023 with 2.0L engines.**

Customer states:

- The EPC light is ON.
- “Drive system: fault” appears in the instrument cluster.

Workshop findings:

The following DTC is stored in the ECM, -J623- (address word 0001):

- **P060C00** Internal Control Module Main Processor Performance” with Symptom code: 44160

Technical Background

Under analysis.

Production Solution

Not applicable.

Service

1. Clear the **DTC P060C00** and return the vehicle to the customer.



Technical Service Bulletin

2. Explain to the customer that a solution is expected to be available by the end of the 1st quarter of 2024 (subject to change) and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*).

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2070571**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2023 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.