



Preliminary Information

PIT5636D SES MIL DTC P1005

Models

| Brand:    | Model:                     | Model Years: | VIN: |     | Engine: | Transmissions: |
|-----------|----------------------------|--------------|------|-----|---------|----------------|
|           |                            |              | from | to  |         |                |
| Chevrolet | Silverado 1500 (New Model) | 2019         | All  | All | All     | All            |
| Chevrolet | Silverado                  | 2020         | All  | All | All     | All            |
| GMC       | Sierra 1500 (New Model)    | 2019         | All  | All | All     | All            |
| GMC       | Sierra                     | 2020         | All  | All | All     | All            |

|                            |                                                                                                                |
|----------------------------|----------------------------------------------------------------------------------------------------------------|
| Involved Region or Country | North America                                                                                                  |
| Condition                  | Some customers may comment on a SES MIL. When the vehicle is checked for DTCs, a P1005 will be set in the ECM. |
| Cause                      | Software error in the fuel pump driver control module.                                                         |

Correction:

GM Engineering has released a new updated fuel pump driver control module to correct this concern. Replace the fuel pump driver control module with updated part number listed in the parts information section below.

Parts Information

| Part Number | Description                                                             | Qty |
|-------------|-------------------------------------------------------------------------|-----|
| 13540028    | Fuel Pump Driver Control Module - Engines: LV3, L3B, L82, L84, L87, L8T | 1   |
| 13540026    | Fuel Pump Driver Control Module - Engines: LM2, L5P                     | 1   |

Warranty Information

For vehicles repaired under the Emission coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Note: Warranty Coverage Codes E and E2 apply to Labor Operation 4087298.

| Labor Operation                                          | Description                             | Labor Time |
|----------------------------------------------------------|-----------------------------------------|------------|
| *4087298                                                 | Replace Fuel Pump Driver Control Module | 0.5 Hr.    |
| *This is a unique Labor Operation for bulletin use only. |                                         |            |

Version History

|          |                                                                                                                                                                                                                                                                               |
|----------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Version  | 5                                                                                                                                                                                                                                                                             |
| Modified | 10/12/2018 - Created on<br>01/17/2020 - Updated the Models, Cause, Correction, Warranty and Parts sections.<br>02/05/2020 - Updated to correct the labor operation.<br>03/21/2023 - Update to the Warranty Section<br>10/17/2023 - Updates to the Warranty and Parts sections |



GENERAL MOTORS

© 2023 General Motors. All Rights Reserved.