



Technical Service Bulletin

01 Engine control unit - "misfires at idle" - 2.0 ltr. TFSI; P030000; P030100; P030200; P030300; P030400
01 23 04 2072274/1 December 13, 2023.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6 allroad	2020 – 2021	All	Not Applicable
RS 6 Avant	2021		

Condition

Customer states:

- The vehicle is running rough in neutral.
- The MIL is illuminated.

Workshop findings:

- After starting the engine, vehicles have misfires across multiple cylinders at an increased idle RPM. (approx. 1200 rpm).

The following entries are stored in the engine control unit J623 (0001)

- **P030X00** – Misfire detected on multiple cylinders.
- **P030100** – Cylinder 1 Misfire.
- **P030200** – Cylinder 2 Misfire.
- **P030300** – Cylinder 3 Misfire.
- **P030400** – Cylinder 4 Misfire.

Technical Background

Updated software for the engine control unit.

Production Solution

Not applicable.

Service



Always use DoIP when flashing a control module via ODIS in supported vehicles.



Technical Service Bulletin

To activate DoIP, select **Administration >> General >> GFF Process >> DoIP communication >> Only allow DoIP communication**.

This setting will automatically reset with the diagnostic session has ended.

You can tell if DoIP is active by observing a red LED on the VAS 6154(A).

1. Follow all instructions on TSB 2071132: *00 Software Version Management (SVM) operating instructions*.
2. Update the J623 (0001) using the SVM action code as listed in the table below if necessary:

Model	Engine Diagnostic Address	Old Software Part Number	Old Software Version (or lower)	New Software Part Number (or higher)	New Software Version (or higher)	SVM Code Input
2019 - 2021A6 2.0L	0001	4K0 906 259 A	0009	4K0 906 259 A	0011	01A267

Warranty

Claim Type:	• 110 Up to 48 Months/50,000 Miles • G10 for CPO Covered Vehicles – Verify Owner • If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2470		
Damage Code:	0039		
Labor Operations:	Software Update (Includes checking for DTCs)	0151 0000	Time stated on the diagnostic protocol (Max 80 TU)
Diagnostic Time:	GFF	No allowance	0 TU
	Test drive before the service procedure	No allowance	0 TU
	Test drive after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2072274/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Technical Service Bulletin

Additional Information

All part and service references provided in this TSB (**2072274**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©**2023 Audi of America, Inc.** All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.