

# MIL ON With DTC P05CE00

**Service Category** Vehicle Interior

**Section** Meter/Gauge/Display

**Market** USA

Toyota Supports  
ASE Certification 

## Applicability

| YEAR(S) | MODEL(S) | ADDITIONAL INFORMATION                 |
|---------|----------|----------------------------------------|
| 2024    | TX350    | VDS(s): AAAA6, AAAB6<br>Engine(s): T24 |

## Introduction

Some 2024 model year TX 350 vehicles equipped with a T24A-FTS engine may exhibit a MIL ON condition with Diagnostic Trouble Code (DTC) P05CE00 (Cold Start “B” Camshaft Position Timing Performance Bank 1). The Engine Control Module (ECM) (SAE term: Powertrain Control Module/PCM) logic has been modified to reduce the possibility of this condition. Follow the Repair Procedure in this bulletin to address this condition.

## Production Change Information

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VIN shown below.

| MODEL  | PLANT | DRIVETRAIN | ENGINE   | PRODUCTION CHANGE EFFECTIVE VIN |
|--------|-------|------------|----------|---------------------------------|
| TX 350 | TMMI  | FWD        | T24A-FTS | TBD                             |
|        |       | AWD        |          | TBD                             |

## MIL ON With DTC P05CE00

### Warranty Information

| OP CODE | DESCRIPTION             | TIME | OFP          | T1 | T2 |
|---------|-------------------------|------|--------------|----|----|
| 800269  | Reprogram the ECM (PCM) | 0.7  | 89661-0EL##* | 8A | 74 |

\*Warranty claim MUST be submitted with the correct 10-digit OFP. Choose the correct OFP for the vehicle being repaired by searching for the parts in the Electronic Parts Catalog using the VIN filter.

#### APPLICABLE WARRANTY

- This repair is covered under the Lexus Federal Emissions Warranty. This warranty is in effect for 96 months or 80,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

### Parts Information

| PART NUMBER  | PART NAME                | QTY |
|--------------|--------------------------|-----|
| 89661-0EL##* | Computer, Engine Control | 1   |

#### NOTE

The ECM (PCM) should NOT be replaced as part of the Repair Procedure.

## MIL ON With DTC P05CE00

### Required Tools & Equipment

| SPECIAL SERVICE TOOLS (SST) | PART NUMBER                 | QTY |
|-----------------------------|-----------------------------|-----|
| Battery Diagnostic Tool     | <a href="#">DCA-8000P T</a> | 1   |

\*Essential SST.

#### NOTE

Additional SSTs may be ordered by calling 1-800-933-8335.

| REQUIRED EQUIPMENT            | SUPPLIER | PART NUMBER  | QTY |
|-------------------------------|----------|--------------|-----|
| Techstream ADVI*              | ADE      | TSADVUNIT    | 1   |
| Techstream 2.0                |          | TS2UNIT      |     |
| Techstream Lite               |          | TSLITEPDLR01 |     |
| Techstream Lite (Green Cable) |          | TSLP2DLR01   |     |

\*Essential SST.

#### NOTE

- Only ONE of the Techstream units listed above is required.
- GTS+ software version 2023.04.003.02 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.
- Use Techstream or an approved J2534 interface to perform flash reprogramming updates. Visit [techinfo.toyota.com](https://techinfo.toyota.com) for more information regarding J2534 reprogramming.

### Calibration Information

| MODEL YEAR | MODEL  | ENGINE           | DRIVE TYPE | CALIBRATION ID |                              |
|------------|--------|------------------|------------|----------------|------------------------------|
|            |        |                  |            | PREVIOUS       | NEW                          |
| 2024       | TX 350 | T24A-FTS (Conv.) | FWD        | 8A2220E19000   | <a href="#">8A2220E19200</a> |
|            |        |                  |            | 8A2220E19100   |                              |
|            |        |                  | 4WD        | 8A2220E18000   | <a href="#">8A2220E18200</a> |
|            |        |                  |            | 8A2220E18100   |                              |

## MIL ON With DTC P05CE00

---

### Repair Procedure

1. Confirm the condition exists.

Does the vehicle exhibit a MIL ON DTC P05CE00 (Cold Start “B” Camshaft Position timing Performance Bank 1) present?

- **YES** — Continue to step 2.
- **NO** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.

2. Use GTS+ to confirm if the ECM (PCM) calibration has been updated.

Is the calibration ID listed in GTS+ the latest ECM (PCM) calibration?

- **YES** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
- **NO** — Continue to step 3.

3. Flash reprogram the ECM (PCM).

#### NOTE

- The battery diagnostic tool MUST be used in Power Supply Mode to maintain battery voltage at 13.5V while flash reprogramming the vehicle.
- For details on how to use the battery diagnostic station, refer to the [DCA-8000 Instruction Manual](#) located at *TIS – Diagnostics – Tools & Equipment – Battery Diagnostics*.

Follow the procedures outlined in [L-SB-0036-22](#) *GTS+ ECU Flash Reprogramming With Security Signature*, and flash the ECM (PCM) with the NEW calibration file update.

4. Using GTS+, clear ANY DTCs and test-drive the vehicle in accordance with the driving pattern described in the confirmation driving pattern to confirm the condition is no longer present.

Refer to TIS, applicable model and model year Repair Manual:

- [2024](#) TX 350:  
*Engine/Hybrid System – Engine Control – “T24A-FTS (Engine Control): SFI System (for Gasoline Model): P001400,P001500,P05CE00; Camshaft Position “B” – Timing Over-Advanced or System Performance Bank 1”*