

REFERENCE:	TSB: 08-046-23 REV. B GROUP 08 - Electrical	Date:	November 9, 2023	REVISION:	08-046-23 REV. A
VEHICLES AFFECTED:	2023 (WL) Jeep Grand Cherokee 2023 (WS) Grand Wagoneer/Wagoneer This bulletin applies to WL vehicles built on or before February 17, 2023 (MDH 0217XX) equipped with one of the following radios: This bulletin applies to WS vehicles built on or before February 14, 2023 (MDH 0214XX) equipped with one of the following radios: • Uconnect 5 NAV W 8.4” Display (Sales Codes UBL, UBR, UER or UEL). • Uconnect 5 NAV W 10.1” Display (Sales Codes UBN or UEN). • Uconnect 5 NAV W 12” Display (Sales Codes UBQ or UEQ).			MARKET APPLICABILITY: ☒ NA ☐ SA ☐ EE ☐ MEA ☐ IAP ☐ CH	
CUSTOMER SYMPTOM:	Customers may experience one or more of the following: • Amplifier module sets Diagnostic Trouble Code (DTC) U0485 - Implausible Data Received Set. • Radio reset (Rearview camera functions normally). • Voice Recognition (VR) inoperable. • Wireless CarPlay® inoperable. • Audio sources inoperable. • Display switches to Nav on VR prompt. • Vehicle Positioning (Lat/Long) inoperable. • Surround View Camera inoperable (Rearview camera functions normally). • Unable to exit FamCam. • Audio Repetition inoperable. • Electric vehicle pages inoperable. • Translated text is incorrect. • Profile avatar changes in Valet Mode. • Display does not return to idle mode after call. • Dynamic rear view camera guidelines inoperable. • FOTA popup won't dismiss. • Ambient Lights Setting inoperable. • Call Status on after all ended Favorites available in valet mode. • SXM® Favorites inoperable. • Tutorial App inoperable. • Audio Repetition stops during incoming calls. • Unable to connect second device. • Unable to exit Seat Comfort popup. • Call does not end on the Instrument Panel Cluster (IPC). • Seat Comfort graphic incorrect. • Headphone button for front passenger display inoperable. • Schedule update inoperable. • USB media source inoperable on front passenger display. • SXM® inoperable. • Wireless Android Auto inoperable. • Media sources duplicated. • Audio unmuted at door close. • Radio freeze (Rearview camera functions normally). • Radio input lagging. • Navigation active with no active route. • Scheduled cabin cooling inoperable. • Incorrect phone repetition displayed. • Navigation routing inoperable. • Unable to exit electric vehicle Pages. • Comfort softkeys incorrect. • Comfort graphic overlap.				

	• Unable to change audio sources. • Audio sources unavailable after profile switch. • No incoming call popup on Uconnect phone. • FamCam image in black and white. • SOS call status banner remains after call ended. • Press and hold inoperable on comfort temperature slider. • Setting preferences will not return to default. • Display input lagging after CarPlay® is connected. • Changed to unselected audio source. • Setting preferences not saved on correct profile. • Translation error in Portuguese. • Memory seats not saved on correct profile. • Audio loss. • Incorrect keyboard in Japanese. • SXM® channel art incorrect. • Rear Seat Entertainment (RSE) audio overlap. • European Media Source (DAB) available on North America vehicles. • Black screen (Rearview camera functions normally). • Unable to delete profile. • Assist call inoperable. • Unable to navigate menu with ongoing SOS call.
CAUSE:	Radio Software

This bulletin supersedes Technical Service Bulletin (TSB) 08-046-23 REV. A, date of issue April 05, 2023, which should be removed from your files. All revisions are highlighted with ****asterisks**** and include an updated Discussion section.

REPAIR SUMMARY:

This bulletin provides information regarding the latest Firmware Over The Air (FOTA) update and provides the service technician an overview of the steps a customer will need to take to complete the update. The radio software will be updated from S26.18 to T25.50.

The national launch for the FOTA is expected to begin February 06, 2023.

DISCUSSION:

****The FOTA Campaign has been put on hold until further notice.****

POLICY:

Information Only

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.