



Technical Service Bulletin

87 Air conditioning does not cool, DTC U032A00 stored in 0008 - HVAC Electronics

87 24 67 2071838/2 February 19, 2024. Supersedes Technical Service Bulletin Group 87 number 23-61 dated October 25, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q4 e-tron, and Q4 Sportback e-tron	2022 – 2024	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Add model year 2024)
1	10/25/2023	Initial publication

Customer states:

The air conditioning does not cool.

Workshop findings:

The following DTC is stored in the HVAC Electronics, -J979- (address word 0008):

- **DTC U032A00:** Software incompatibility with A/C compressor Control Module.

Technical Background

Restricted air conditioning function due to a loss of adaptation in the -J842- A/C Compressor Control Module.

Production Solution

This bulletin will be updated when more information is available. A solution is currently under development.

Service

Condition verification procedure

- Do not replace the air conditioning compressor. Compressor replacement will not solve this issue.



Technical Service Bulletin

- Follow the ODIS test plan for DTC U032A00 “Calibrate the A/C Compressor” fully. This will reinitialize the compressor adaptation and restore cabin cooling.
- Explain to the customer that this symptom could reoccur.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	8734		
Damage Code:	0040		
Diagnostic Time:	GFF	0151 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB 2071838/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (**2071838**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes



Technical Service Bulletin

at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.