



Technical Service Bulletin

01 Repair Authorization MIL on, DTC P044200 Stored in the ECM

01 24 10 2069166/3 February 23, 2024. Supersedes Technical Service Bulletin Group 01 number 23-77 dated September 12, 2023 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5, and Q5 Sportback	2022 – 2024	All	2.0l engine

Condition

REVISION HISTORY		
Revision	Date	Purpose
3	-	Revised header (Added MY24)
2	9/12/2023	Revised <i>Service</i> (Updated instructions)
1	01/17/2023	Initial publication

Customer states:

- MIL is on.

Workshop findings:

The following DTC may be stored in the ECM, -J623- (address word 0001):

- DTC: P044200:** EVAP Emission Control System (Small Leak) Leak Detected (Passive/Active).

Technical Background

Various parts have been replaced under warranty for the condition noted above, but no issues were identified with these parts. In order to gather information on the DTC codes for the vehicles listed above, we are asking that you contact the Audi Technical Assistance Center (TAC) before replacing any parts. This will assist us in diagnosing any potential issues with the condition noted above.

Production Solution

No changes to production have been made, as no issue has been identified.

Service

Audi of America is requesting your cooperation in supplying us with technical information regarding this condition.



Technical Service Bulletin

- Verify the condition.
- Perform EVAP testing per the ELSA Repair Manual: *Engine>>Using the Evaporative Emissions tester >> 20 Fuel Supply >> Fuel System EVAP Leak Test >> EVAP System Leak Test, Vehicles with Fuel Tank Leak Detection Control Module (NVLD) >> EVAP system testing.*
- If no leaks are detected continue to perform the populated test plan in GFF.
- Once the test plan is completed recheck the status of the DTC, if it is still static contact TAC. If it is passive/sporadic perform no repairs and release the vehicle.
- If the vehicle is within the New Vehicle Limited Warranty, P044200 has been set in the past OR the fault is still static after performing the GFF test plan contact TAC before proceeding.
- Please attach the DTC and diagnostic log to the TAC Web Ticket, and note the tool used to test the EVAP system for leaks.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (**2069166**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

© **2024 Audi of America, Inc.** All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.