



# Technical Service Bulletin

**01 Car jerks/bucks or hesitates while driving DTCs P023600 and/or P010600 are stored in the ECM**  
01 24 11 2062323/3 March 4, 2024. Supersedes Technical Service Bulletin Group 01 number 21-13 dated October 20, 2021 for reasons listed below.

| Model(s) | Year        | VIN Range | Vehicle-Specific Equipment |
|----------|-------------|-----------|----------------------------|
| A6       | 2019 – 2022 | All       | 2.0l engine                |

## Condition

| REVISION HISTORY |            |                                                                          |
|------------------|------------|--------------------------------------------------------------------------|
| Revision         | Date       | Purpose                                                                  |
| 3                | -          | Revised header (Removed model year 2018)                                 |
| 2                | 10/20/2021 | Revised header (Added Model Year 2022 and removed VIN break for MY 2021) |
| 1                | 02/15/2021 | Initial publication                                                      |

### Customer states:

- The vehicle feels as if it is hesitating, is low on power or is bucking/jerking while driving.
- The MIL may also be illuminated.

### Workshop findings:

- The yellow wire on the electrical connector of the charge pressure sender is damaged.

One or more of the following DTCs may be stored in the engine control module (ECM), J623 (address word 0001):

- **DTC P010600** (Manifold Abs.Pressure or Bar.Pressure Range/Performance).
- **DTC P023600** (Turbocharger Boost Sensor (A) Circ. Range/Performance).

## Technical Background

Due to the routing of the wiring and the length of wiring that is uncovered, the wiring may become damaged due to vibrations.

## Production Solution

The harness is secured in place with textile tape during production.

## Service



# Technical Service Bulletin

---

If the customer concern and one or more of the faults listed above is present, inspect the wires at the G31 sensor.

If there are no issues found at G31 connector this TSB does not apply. Please proceed with standard diagnosis.



**Tip: It may be necessary to disconnect or de-pin the wires from the G31 connector to check for proper crimping and seating of the pins.**

1. If damage is found to the pins or wire at the G31 boost pressure sensor, repair the harness using VAS 1978B (Figure 1).

Please use gold-plated contacts to repair the damaged wire(s) (000 979 025 EA).

Ensure there is sufficient slack in the harness to prevent future issues.



*Figure 1. Wire is broken at G31 sensor.*



# Technical Service Bulletin

---

2. Following repairs, the harness must be wrapped with textile tape **N 105 920 02**.

Apply the textile tape starting at the wiring below the connector. Ensure the wires are kept flat to avoid over stressing the pins (Figure 2).



*Figure 2. Harness is wrapped using textile tape 105 920 02.*

3. Wrap the tape in the direction of the connector keeping it **flat** (Figure 3).



*Figure 3. Wrapping the connector base.*



# Technical Service Bulletin

4. The tape must extend far enough to cover the connector base (Figure 4).



**Figure 4.** Wrapping the connector base part 2.

5. Continue to wrap the exposed wires down the harness and slightly overlap the existing harness tape (Figure 5).



**Figure 5.** Completed harness wrapping.

## NOTICE

Parts replacement does not solve this issue. Claims for replaced parts (e.g., G31 sensor or turbocharger) will be subject to review.

## Warranty

|                        |                                                                                                                                                                                                                                                     |
|------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Claim Type:</b>     | <ul style="list-style-type: none"><li>• 110 up to 48 Months/50,000 Miles.</li><li>• G10 for CPO Covered Vehicles – Verify Owner.</li><li>• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li></ul> |
| <b>Service Number:</b> | 9709                                                                                                                                                                                                                                                |
| <b>Damage Code:</b>    | 0015                                                                                                                                                                                                                                                |



# Technical Service Bulletin

|                          |                                          |              |                                                    |
|--------------------------|------------------------------------------|--------------|----------------------------------------------------|
| <b>Labor Operations:</b> | Check and repair engine wiring harness   | 9752 4199    | 40 TU                                              |
| <b>Diagnostic Time:</b>  | GFF/Guided Functions                     | 0150 0000    | Time stated on the diagnostic protocol (Max 50 TU) |
|                          | Road test prior to the service procedure | No allowance | 0 TU                                               |
|                          | Road test after the service procedure    | 0121 0004    | 10 TU                                              |
| <b>Claim Comment:</b>    | As per TSB 2062323/3                     |              |                                                    |

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Required Parts and Tools

| Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. |                                                                    |               |
|-----------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|---------------|
| Part Number                                                                                         | Part Description                                                   | Quantity      |
| See ETKA                                                                                            | Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual | See ETKA/ELSA |
| N 10592002                                                                                          | Textile Tape                                                       | .10           |
| 000979025EA                                                                                         | Gold-plated contact                                                | 01            |
| 000979940                                                                                           | Butt connector                                                     | 01            |

| Tool Number       | Tool Description                                         |
|-------------------|----------------------------------------------------------|
| VAS 1978B         | Wire harness repair set                                  |
| VAS 6160/VAS 6150 | VAS tester with the current version of ODIS (Windows 10) |

## Additional Information

All parts and service references provided in this TSB (**2062323**) are subject to change and/or removal.

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.