

 HYUNDAI Technical Service Bulletin	GROUP EV Systems	NUMBER 24-EV-001H
	DATE MARCH 2024	MODEL(S) IONIQ PLUG-IN HYBRID (AE PHEV)
SUBJECT: ECU SOFTWARE UPDATE FOR DTC U1341		

Description: This bulletin provides the procedure to update the ECU software on certain 2021-2022MY IONIQ Plug-in Hybrid (AE PHEV) vehicles that may exhibit a warning light with DTC U1341 due to communication issues with the Integrated Electronic Brake (IEB) during charging in IG3 mode. Follow the procedure in this TSB to update the ECU software logic.

- DTC Info: U1341 - ECU-IEB Communication Delay

Applicable Vehicles:

- 2021–2022MY IONIQ Plug-in Hybrid (AE PHEV)

GDS Information:

System	Event #	Description
Engine	1039	AE PHEV ECU S/W TO IMPROVE FOR DTC U1341

(*or use a later available event as listed in the GDS ECU Update screen if one is available.)

Warranty Information:

Model	Op. Code	Operation	Op. Time	Casual Part	Nature Code	Cause Code
Ioniq Plug-in Hybrid (AE PHEV)	39110FH1	ECU Update	0.3 M/H	Refer to WebDCS for applicable part to labor op code combination	I14	ZZ3

NOTE 1: Normal warranty applies.

NOTE 2: Submit claim on Claim Entry Screen as “Warranty” type.

NOTE 3: This TSB includes Repair validation photos. Op times include VIN, Mileage, and photo capture of the “ECU update complete” screen as outlined in the Digital Documentation Policy.

NOTE 4: If a part is found in need of replacement while performing this TSB and the affected part is still under warranty, submit a separate claim using the same repair order. If the affected part is out of warranty, submit a Prior Approval request for goodwill consideration prior to performing the work.

Service Procedure:

STUI

This TSB includes Repair validation photos. Refer to the latest Warranty Digital Documentation Policy for requirements.


NOTICE

You must initially perform the GDS ECU update in Auto Mode.

- If the ECU update starts but then fails in Auto Mode, perform the update in Manual Mode to recover.

NOTICE**GDS Vehicle Battery Low Voltage Warning:**

If voltage is below 12 volts per the GDS warning, then select **Back** and attach a battery maintainer or run the vehicle for at least 20 minutes to ensure an adequate battery charge for reliable update results. Turn ignition back **ON**, and then retry the ECU update again.



1. Perform the ECU update in Auto Mode.

Use the **ID Check** to verify the ROM ID before updating the software.

**Information**

Refer to TSB 15-GI-001 for additional information for the ECU update Procedure For Tablet-Based GDS Mobile.




2.

STUI



Take a screenshot of the “ECU update complete” screen using your tablet and upload to STUI.



3. After the ECU update process shows 100% complete, cycle the ignition key to **OFF** for at least 10 seconds to reset the control unit.
4. Perform an **All Systems Fault Code** search and erase DTC history that had incidentally occurred from the ECU update.
5. Start the vehicle in **Ready** mode to confirm proper operation of the vehicle.

ROM ID Information Table:

Model	MY	System	ECU Part Number	ROM ID	
				Old	New
AE PHEV	2021	Engine	39110-03918	AEDBS6PGXG50	AEDFS6PGXG9F
	2022		39110-03932	AEDCS6PGXG61	AEDCS6PGXG9F

Manual Mode Password:

ECM Menu	Password
AE PHEV ECU 39110-03918	9639
AE PHEV ECU 39110-03932	9640