



SERVICE ACTION

Global Service Action
Number: N881

Subject: Powertrain Control Module (PCM) Software Update	Publication No.: N881
	Model: Discovery (LR)
	Model Year: 2017 - 2020
	Model: Range Rover (LG)
	Model Year: 2017 - 2020
	Model: Range Rover Sport (LW)
	Model Year: 2017 - 2020
	Model: Range Rover Velar (LY)
	Model Year: 2018 - 2020
Date of Issue: 26 March 2024	

To:	Jaguar Land Rover North America, LLC and Jaguar Land Rover Canada ULC.
For the Attention of:	The approved JLR retailer/authorized repairer.
Important:	NOTE: The information in this campaign is intended for use by professional technicians. If you are not a JLR retailer/authorized repairer, do not assume that a condition described affects a specific vehicle. Contact an authorized JLR retailer/authorized repairer to determine if this campaign applies to a specific vehicle. This campaign replaces N747 with immediate affect.

FOR THE ATTENTION OF ALL:

DESCRIPTION OF ISSUE

A potential concern has been identified on specific vehicles within the above vehicle range.

On certain 2017 model year to 2020 model year Land Rover and Range Rover vehicles the Malfunction Indicator Lamp (MIL) may illuminate if the vehicle is refueled within 15 seconds of turning the engine off. Diagnostic Trouble Codes (DTC) P0496-00 may be stored in the Powertrain Control Module (PCM).

ACTION TO BE TAKEN

At the next opportunity, you are requested to repair the vehicle.

Check the JLR Warranty Portal to make sure affected vehicles are correctly identified prior to starting this campaign. The Warranty Portal will be updated to reflect only those vehicles affected.

An owner may indicate that a repair has already been completed for this concern, in which case the full cost of the repair should be reimbursed. Refer to the warranty section of this campaign for details of the Customer Reimbursement and Related Damage Process. At the time of confirming a booking for a vehicle repair, make sure you check the Warranty Portal to confirm if there are any other outstanding campaigns, to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed in one visit.

FOR THE ATTENTION OF NORTH AMERICAN TERRITORIES ONLY:

Visit the British Brands Sales Suite (BBSS) website for a list of affected vehicles at your JLR retailer/authorized repairer. Unsold vehicles must be repaired prior to handover of the vehicle for retail sale.

Yours faithfully

Steve Oldham

Global Customer Care Quality Director

SERVICE INSTRUCTION

- N881

SROs

Description	SRO	Time
Powertrain Control Module (PCM) software update	85.18.03	0.2
Drive in/drive out	02.02.02	0.2

NOTE:

Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

Warranty Information

Warranty claims should be submitted quoting program code N881 with the relevant option code from the table below. As option codes are used there is no requirement for you to enter SROs or parts, these are included for information only.

Program Code	Option	Description	SRO	Time
N881	A	PCM software update	85.18.03	0.2
N881	B	PCM software update Drive in/drive out	85.18.03 02.02.02	0.2 0.2

NOTE:

The option that contains the drive in/drive out allowance may only be claimed when the vehicle has been brought back into the workshop for this action alone to be undertaken.

Warranty claims should be submitted in accordance with the current JLR Global Warranty Manual, and its amendments, unless stated otherwise in this bulletin.

Customer Reimbursement and Related Damage Process

NOTE:

If there is a requirement to claim for related/consequential damage or customer reimbursement, refer to the related instruction that can be found in TOPIx (in the Search box, search for 'Related Damage Claim' and open the related bulletin link).

Table of Contents
REMOVAL AND INSTALLATION: SERVICE INFORMATION
REMOVAL AND INSTALLATION: DIAGNOSTIC INSTRUCTION - USING TOPIx CLOUD DIAGNOSTICS

SERVICE INFORMATION

1. [Diagnostic Trouble Codes \(DTC\)](#) P0496-00 will be stored in the [PCM](#) if the vehicle has been refueled within 15 seconds of turning the engine off. [DTC](#) P0496-00 will cause the [Malfunction Indicator Lamp \(MIL\)](#) to be illuminated on the Instrument Panel Cluster. The [DTCs](#) will be cleared as part of the [PCM](#) software update application completed in the Diagnostic Instruction. If the [MIL](#) remains illuminated on the Instrument Panel Cluster after completing the Diagnostic Instruction it is not related to this concern and further investigation must be completed as part of a separate repair.

DIAGNOSTIC INSTRUCTION - USING TOPIX CLOUD DIAGNOSTICS

NOTE:

Modules already at the latest software level will not be available for update. If all module updates below cannot be completed due to already being at the latest software level, email jlrcamp@jaguarlandrover.com with the [Vehicle Identification Number \(VIN\)](#) and campaign reference, for the campaign to be closed.

1. Connect the JLR approved diagnostic equipment and the JLR approved battery support unit.

2.

NOTE:

Only complete this step if the vehicle is in transit mode.

Select the link to disable transit mode.

3.

NOTE:

Only complete this step if the vehicle is in transit mode.

Select the link to disable transit mode.

4. Update the [PCM](#) -

5.

NOTE:

If required.

Select the link to enable transit mode.

6.

NOTE:

If required.

Select the link to enable transit mode.

7. Follow all on-screen instructions to complete the task.

8. Disconnect the JLR approved diagnostic equipment and the JLR approved battery support unit.