



TECHNICAL SERVICE BULLETIN

Classification:	Reference:	Date:
DA23-008A	NTB24-002A	March 1, 2024

DTCS C1B53-04 AND/OR C1B54-04 STORED IN THE ADAS CONTROL MODULE

This bulletin has been amended. See **AMENDMENT HISTORY** on the last page.
Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2019-2024 Kicks (P15)
APPLIED DATES: 2019-2023 Kicks – All
2024 Kicks – Built on or before January 19, 2024
APPLIED SYSTEMS: Side Obstacle Warning System

IF YOU CONFIRM

DTCs C1B53-04 for “SIDE RDR R MALF” and/or C1B54-04 for “SIDE RDR L MALF” are stored as CURRENT in the ADAS Control Module,

AND

The ESM diagnosis leads to Side Radar Sensor replacement.

ACTION

If replacing one or more affected Side Radar Sensor(s), refer to the **SERVICE PROCEDURE** in this bulletin to apply a strip of foam around each of the Side Radar Sensors before reinstalling the rear bumper fascia.

HINT: This bulletin does not cover the diagnosis or replacement of the Side Radar Sensors.

IMPORTANT: The purpose of **ACTION** (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire **SERVICE PROCEDURE** as it contains information that is essential to successfully completing this repair.

Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

IMPORTANT: The following steps and figures show the passenger (RH) side, the driver (LH) side is similar.

1. Clean the area shown in Figure 1 with isopropyl alcohol.




Figure 1

2. Separate the four (4) foam strips from the **PARTS INFORMATION**.



Figure 2

3. Using two (2) foam strips, place the foam strips in the locations shown in Figure 3.




Figure 3

4. Repeat steps 1 - 3, starting on page 2 for the driver (LH) side.
5. Install the rear bumper fascia.
 - Refer to the ESM: **BODY EXTERIOR, DOORS, ROOF & VEHICLE SECURITY > EXTERIOR > REMOVAL AND INSTALLATION > REAR BUMPER > Removal and Installation**

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
SEAL – INSPECTION HOLE COVER (Foam strips)	74847-5RH0B	1

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Apply Foam Side Radar - One	(1)	SX24AA	ZE	32	0.7
Apply Foam Side Radar - Both		SX25AA			

- (1) Reference the electronic parts catalog and use the Sensor Assy Side Obstacle Warning (284K0-****) as the Primary Failed Part (**PFP**).

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
January 16, 2024	NTB24-002	Original bulletin published
March 1, 2024	NTB24-002A	APPLIED VEHICLES revised and APPLIED DATES added

