



Preliminary Information

PIT6144 Diagnostic Tip for Service Leveling System Message And DTC: C1197

Models


Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	Escalade Models	2021 - 2024	All	All	All	All
Chevrolet	Suburban	2021 - 2024	All	All	All	All
Chevrolet	Tahoe	2021 - 2024	All	All	All	All
GMC	HUMMER EV	2022 - 2024	All	All	All	All
GMC	HUMMER EV SUV	2024	All	All	All	All
GMC	Yukon Models	2021 - 2024	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	F47 Air Ride Adaptive Suspension
Condition	Some customers may comment on following concerns: - Air leveling suspension is inoperative - Service Leveling System message displayed in the DIC - DTC: C1197 SYM 00
Cause	This condition may be caused by a plugged or pinched air inlet hose to the air suspension compressor assembly.

Correction:

If you experience one of the conditions above, please check the following as this may be causing your concern:

Inspect the air suspension compressor air inlet hose for being pinched or twisted and preventing air from entering the air suspension compressor. The air inlet hose assembly is shown as #17 below. If you find the air inlet hose pinched or twisted, repair as needed.



Example of twisted hoses on the 2024 Hummer EV



Example of a pinched hose on a 2023 Cadillac Escalade below:



Version History

Version	1
Modified	03/28/2024 - Created on.



© 2024 General Motors. All Rights Reserved.