



# Technical Service Bulletin

---

**19 PSS Engine: Radiator blind - fault. Maximum speed limit to 10 mph A3 DTC's P05AF00, P05B200, P05A000, P05A300**

19 24 56 2073088/1 April 5, 2024.

| Model(s)         | Year        | VIN Range | Vehicle-Specific Equipment |
|------------------|-------------|-----------|----------------------------|
| A3, S3, and RS 3 | 2022 - 2024 | All       | Not Applicable             |

## Condition

### Customer states:

There is a message in instrument cluster: Radiator blind fault Maximum speed limited to 10 mph. please contact workshop.

### Workshop findings:

- The following DTC's are stored in ECM, J623 (address word 0001):
- **P05AF00** – active radiator blind 2 sticks open – with symptom 28397.  
and/or
- **P05B200** – active radiator blind 2 lost communication – with symptom 2840.  
and/or
- **P05A000** – active radiator blind 1 sticks open – with symptom 28396.  
and/or
- **P05A300** – active radiator blind 1 lost communication – with symptom 28408.

## Technical Background

Engine control unit issue

- In rare cases the following message may be shown in the cluster Radiator blind fault Maximum speed limited to 10 mph. please contact workshop.
- The maximum speed limit should specify 100 mph rather than 10 mph.
- Be aware that the complaint may reappear at speeds greater than 100 mph.

## Production Solution

Improved software to be released.

## Service



# Technical Service Bulletin

- If no fault is found with the component using GFF, then the memory entry can be deleted.
- Explain to the customer that a solution is expected to be available by the end of the 4th quarter of 2024 (subject to change) and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
- Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> *Service*).

 **NOTICE**

**In many cases, the complaint is fixed after an ignition cycle.**

## Warranty

|                         |                                                                                                                                                                                                                                                     |              |                                                    |
|-------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|----------------------------------------------------|
| <b>Claim Type:</b>      | <ul style="list-style-type: none"><li>• 110 up to 48 Months/50,000 Miles.</li><li>• G10 for CPO Covered Vehicles – Verify Owner.</li><li>• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li></ul> |              |                                                    |
| <b>Service Number:</b>  | 1935                                                                                                                                                                                                                                                |              |                                                    |
| <b>Damage Code:</b>     | 0016                                                                                                                                                                                                                                                |              |                                                    |
| <b>Diagnostic Time:</b> | GFF                                                                                                                                                                                                                                                 | 0150 0010    | See SRT with associated operations                 |
|                         | Software update                                                                                                                                                                                                                                     | 0150 0060    | Time stated on the diagnostic protocol (Max 80 TU) |
|                         | Road test prior to service procedure                                                                                                                                                                                                                | No allowance | 0 TU                                               |
|                         | Road test after service procedure                                                                                                                                                                                                                   | No allowance | 0 TU                                               |
| <b>Claim Comment:</b>   | As per TSB 2073088/1                                                                                                                                                                                                                                |              |                                                    |

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All part and service references provided in this TSB (**2073088**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.



# Technical Service Bulletin

---

©2024 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.