

Coupling of the rear axle differential has reached its wear limit

Topic number	LI35.31-P-077429
Version	1
Function group	35.31 - Rear axle center assembly
Date	5/7/24
Validity	118, 177, 247 with engine 260, 282, 654 with code M005 (Vehicles with 4MATIC/all-wheel drive)
Reason for change	

Complaint

Instrument cluster message "4MATIC inoperative".

The following fault code may be present in all-wheel drive control unit N15/17:

P147354 - Erroneous adaptation of the transfer case. The calibration is missing.

P14759A - The coupling of the transfer case has malfunctioned. The operating conditions for the component or the system have not been fulfilled.

Cause

Coupling of the rear axle differential has reached the wear limit or a coupling defect is present.

Remedy

Please read off the installed part number of the rear axle differential.

For model designations (flat model series and not AMG 35 variants) 118345; 118347; 118613; 118615; 118647; 177013; 177015; 177045; 177047; 177145; 177147; 177188; 177945; 247013; 247045; 247047, the following applies:

- If part number A2473502702 is not installed, the coupling package can be replaced. To this end, a repair kit has been added as a replacement part.
- If part number A2473502702 is installed, the installation of the coupling package repair kit is not permissible and the rear axle differential should be replaced.

For model designations (high model series and AMG 35 variants) 177151; 177051; 118351; 118651; 177951, the following applies:

- If one of the part numbers A2473502702; A2473502503; A2473504504 has not been installed, the coupling package can be replaced. To this end, a repair kit has been added as a replacement part.
- If one of the part numbers A2473502702; A2473502503; A2473504504 has been installed, the installation of the coupling package repair kit is not permissible and the rear axle differential should be replaced.

If the removed friction plates show signs of a pad becoming detached, please contact product support.

For example pictures of the pad becoming detached at the friction plates, see the attachment.

Attachments	
File	Description
Beispielbild Reibbelag Ablösung.pdf	

WIS-References		
Document number	Title	Note
AR35.31-P-0002MFA	Remove/install multiplate clutch of the rear axle differential	

Symptoms
Power transmission > Transfer case > Function > Electrical fault/Fault code

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 247 350 90 04			MULTIPLATE CLUTCH RE-PAIR KIT			X

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note